Phase I Historic Resource Survey Social Circle, Georgia

August 2012





The University of Georgia College of Environment + Design Center for Community Design & Preservation Phase I Historic Resource Survey Social Circle, Georgia

Credits

Report Submitted to:

Georgia Department of Transportation Office of Environmental Services One Georgia Center, 16th Floor 600 West Peachtree Street, NW Atlanta, GA 30308

Report Prepared by:

Center for Community Design & Preservation (CCDP) http://www.ced.uga.edu/pso 225 W Broad Street Athens, GA 30062

Pratt Cassity – Principal Investigator Laura Kviklys – Project Coordinator

Emily Laborde, MHP, Field Surveyor, Report creation

Fielding Link, Master of Landscape Architecture Candidate, Field Surveyor, Report Creation Kristin Porter, Master of Historic Preservation Candidate, Field Surveyor, Report Creation Milton Perry, Master of Landscape Architecture Candidate, Field Surveyor, Report Creation Thomas Peters, Master of Landscape Architecture Candidate, Field Surveyor, Report Creation Caty Rushing, Master of Historic Preservation Candidate, Report Creation Eleonora Machado, CCDP Graphics Coordinator, Report design and layout

Table of Contents

Page 4	List of Figures
Page 4	List of Tables
Page 5	Introduction
Page 7	Project Description
Page 8	Methodology
Page 9	National Register of Historic Places Evaluation Criteria
Page 11	Survey Results
Page 31	Integrity
Page 33	Conclusion
Page 34-219	All Identified Resources
Page 220	Bibliography

List of Figures

Figure 1. Survey Area for the City of Social Circle	Page 6
Figure 2. All Identified Resources within Social Circle, GA	Page 12
Figure 3. All Identified Resources by Date	Page 13
Figure 4. National Register for Historic Places Eligibility of Resources	Page 14

List of Tables

Table 1.	Field Survey Results, Description of all Identified Resources	Pages 15-23
Table 2.	Field Survey Results, All Identified Resources, Use	Page 23
Table 3.	Field Survey Results, All Identified Resources, Use Percent-	Page 24
	ages	
Table 4.	Field Survey Results, All Identified Resources, Age Distribu-	Page 25
	tion	
Table 5.	Field Survey Results, All Identified Resources,	Page 26
	Construction Date by Percentage	
Table 6.	Field Survey Results, All Identified Resources,	Page27
	Residential Building Types	
Table 7.	Field Survey Results, All Identified Resources,	Page 28
	Residential Building Type By Percentage	
Table 8.	Field Survey Results, All Identified Resources,	Page 29
	Architectural Styles	
Table 9.	Field Survey Results, All Identified Resources,	Page 30
	Architectural Styles by Percentage	

Introduction

What is a cultural resource survey?



The Georgia Historic Resources Survey is an ongoing, statewide survey of buildings, sites, structures, and objects of historical, architectural and cultural significance. The Georgia Survey is one of the programs administered by the Historic Preservation Division of the Department of Natural Resources (HPD).

Completed surveys can be used to identify individual buildings and districts for possible listing in the Georgia Register of Historic Places; assist the preservation efforts of Georgia's Certified Local Governments; support local designations of buildings and districts; expedite review by governmental agencies; aid preservation and land-use planning; and promote research of the state's history and architecture.

A goal of an historic resources survey is to collect a minimum level of information needed statewide for preservation activities. This basic, standard survey does not gather all the kinds of information needed in local preservation planning, environmental review, National Register nominations, or historical research, but serves as the foundation for these preservation activities.¹

1<>. "Georgia Historic Resources Survey Manual," Atlanta: Georgia Department of Natural Resources, Historic Preservation Division, 2000.



Project Description

The Center for Community Design and Preservation (CCDP) located within the University of Georgia's College of Environment + Design (CED) conducted a Phase I historic resource survey of the City of Social Circle, Georgia, in August 2012. The study was initiated as mitigation for an adverse effect to the setting of the Social Circle Historic District due to the replacement of the structurally deficient bridge on SR 11/S. Cherokee Road over the CSX Railroad in downtown Social Circle, Georgia (GDOT P.I. #132980). The study was sponsored by the Georgia Department of Transportation, the Federal Highway Administration, and the State Historic Preservation Office of the Georgia Department of Natural Resources. The project area covered the approximately 11.2 square miles within city limits which is located in both Walton and Newton Counties. The city is approximately 45 miles east of Atlanta and approximately four miles due north of Interstate 20.

The resource survey was performed by historic preservation professionals, and graduate students in the Maters of Historic Preservation program (MHP) and the Masters of Landscape Architecture program (MLA) at the CED. The survey consisted of background research, with particularly heavy focus on the 2002-2003 DNR survey for the City of Social Circle, and the 1981 National Register of Historic Places Inventory of Social Circle. The survey also included windshield and pedestrian field work, data collection and analysis. The survey identified and documented all resources within city limits of Social Circle that are 45 years old or older, and any Ranch House with a construction date prior to 1970.

The information collected by the field survey was entered into Georgia's Natural, Archaeological, and Historic Resources Geographical Information System (GNAHRGIS), a web-based geographical information system designed to store and display information about Georgia's cultural resources. GNAHRGIS is the repository for all of the current statewide historic resource data. The survey information was entered under survey ID 2207, "New Survey for Social Circle, Ga" and can be accessed at www.gnahrgis.org.

Methodology

The survey was conducted according to the procedures outlined in The Georgia Historic Resources Survey Manual. Prior to fieldwork, an evaluation of the survey area was conducted using the 2002-2003 Georgia Historic Resources survey report of the City of Social Circle. The survey area was assessed for properties listed in the National Register for Historic Places, and GIS data obtained from the City of Social Circle was used to identify potentially historic parcels and structures in combination with USGS base maps indicating structures built prior to 1981.

The area was surveyed over the course of several days with a systematic coverage of the Each resource within the assigned boundaries was assessed for historic project area. significance and architectural integrity. A Georgia Historic Resources survey form was completed for all buildings having a minimum level of architectural integrity. A structure with architectural integrity is one that generally maintains its original location, design, setting, materials, workmanship, feeling and association. Properties with a significant loss of physical integrity, or those lacking historic significance were not surveyed (i.e., outbuildings without a primary structure or manufactured homes). The physical condition of structures was not a consideration for identification for resources which retained architectural integrity. All identified and documented resources were 45 years old or older, with the exception of Ranch Houses with a construction date prior to 1970. All properties were surveyed from the public right of way and assigned an identification number then documented with the completion of a Georgia Historic Resources survey form, as well as photo documentation and corresponding georeferencing data. The survey form includes information about the use, style, floor plan, materials, context, physical description and an accurate age determination of date of construction and additions. Dates of construction are given in ten-year increments because of the difficultly to pinpoint specific dates of construction completion based solely on field analysis, and the prevalence of stylistic element changes. Unless specifically noted on the structure itself, the surveyors used sources like, Lee and Virginia McAlester's A Field Guide to American Houses, the Georgia Historic Resources Survey Manual, Georgia's Living Places and A Visual Guide to Architecture by Francis D. K. Ching to make age determinations and architectural style and type identifications.

Criteria for Evaluation

National Register for Historic Places

Each resource was evaluated for potential listing in the National Register of Historic Places (NRHP). Each resource must be at least 45 years of age or older, and meet the criteria outlined in the National Register Bulletin How to Apply the National Register Criteria for Evaluation published by the U.S Department of Interior, National Park Service. Cultural resources can be defined as eligible for the NRHP if they:

- A. Are associated with events that have had a significant contribution to a broad pattern of history; or
- B. Are associated with the lives of persons significant in the past;
- C. Embody distinctive characteristics of a type, period, or method of construction, or represent the work of a master, possess high artistic values, or represent a significant and distinguished entity whose components may lack distinction; or
- D. Have yielded or may be likely to yield, information important to history or prehistory.¹

Ordinarily cemeteries, birthplaces, or graves of historical figures, properties owned by religious institutions or used for religious purposes, structures that have been moved from their original locations, reconstructed historic buildings, properties primarily commemorative in nature, and properties that have achieved significance within the last 50 years are not considered for the National Register. However, properties will qualify if they are integral parts of districts that do meet the criteria or they fall within the following categories:

- a. A religious property deriving primary significance from architectural or artistic distinction or historical importance; or
- b. A building or structure removed from its original location but which is significant primarily for architectural value, or which is the surviving structure most importantly associated with a historic person or event; or
- c. A birthplace or grave of a historical figure of outstanding importance if there is no appropriate site or building directly associated with his or her productive life; or
- d. A cemetery which derives its primary significance from graves or persons of transcendent importance, from age, from distinctive design features, or from association with historic events; or
- e. A reconstructed building when accurately executed in a suitable environment and presented in a dignified manner as part of a restoration master plan, and when no other building or structure with the same association has survived; or
- f. A property achieving significance within the last 50 years if it is of exceptional importance.

For a property to qualify for the National Register it must meet one of the National Register Criteria for Evaluation by:

- Being associated with an important historical context and
- Retaining historic integrity of those features to convey its significance.

To determine whether a property or site retains integrity, it needs to be evaluated for the aspects of its location, design, setting, workmanship, materials, feeling, and association to convey its historic significance.²

¹The Criteria for Evaluation are found in the Code of Federal Regulations, Title 36, Part 60, reprinted in U.S. Department of Interior, National Park Service,

National Register Bulletin: How to Apply the National Register Criteria for Evaluation, Washington, D.C., 1997, p. 2-3. ²A complete list of areas of significance can be accessed at http://www.nps.gov/nr/publications/bulletins/nrb15/nrb15_5.htm


















Survey Results


The survey team reexamined resources documented in the 2002-2003 HPD survey of Social Circle, as well as those that have surpassed the 45 year age limit. The survey documented the current architectural integrity of the existing Social Circle Historic District and surrounding areas in order to place post war structures in a historic context. The Social Circle Historic District is comprised of residential, commercial, and industrial structures, including the historic downtown, and date to the turn of the 20th century.


A total of 370 resources were documented that meet and maintain a minimum level of age¹, integrity, and significance. The construction date of all identified resources range from the mid-1840s to the mid-1980s; the period with the most extant resources is from 1955-1974 with 53 (14%), followed by 1900-1914 with 43 (12%). The variance in building type and architectural styles exhibited throughout Social Circle is typical for 19th century towns located along railroads. The majority of identified resources are single family dwellings (83%), with the most common types being the Ranch House (31%) and the Saddlebag (8.7%). The majority of all resources (65.6%) did not exhibit any type of high style architecture, and are considered to be of no academic style.²

2 In the following sections, a resource denoted as Potentially Eligible are those which have reached 45 years of age but not 50 years of age, or which warrant further academic research before offical lising in the National Register

¹ Age refers to a building date prior to 1967 (45 years at the time of the field survey), or a construction date prior to 1970 for all Ranch Houses.







PAGE 14 August 2012 | Phase | Historic Resource Survey | Social Circle, Georgia * Potentially Eligible resources denote those that have reached 45 years of age but not 50 years of age, or which warrant further academic research before offical lising in the National Register

ALL IDENTIFIED RESOURCES

Resource ID	Description	NRHP Recommendation	GNARHGIS ID
SC-1	Willow Spring Church Road Cemetery	Eligible	240247
SC-2	Saddlebag: 2 Door	Listed	240250
SC-3	Saddlebag: 2 Door	Listed	240254
SC-4	Double Shotgun	Listed	240257
SC-5	Double Shotgun	Listed	240258
SC-6	Double Pen	Listed	240263
SC-7	Hipped Bungalow	Listed	240264
SC-8	Saddlebag: 2 Door	Listed	240266
SC-9	Saddlebag: 2 Door	Listed	240267
SC-10	Saddlebag: 2 Door	Listed	240269
SC-11	Saddlebag: 2 Door	Listed	240273
SC-12	Saddlebag: 2 Door	Listed	240276
SC-13	Central Hallway Cottage	Listed	240277
SC-14	Saddlebag: 2 Door	Listed	240301
SC-15	Saddlebag: 2 Door	Listed	240302
SC-16	Saddlebag: 2 Door	Listed	240303
SC-17	Saddlebag: 2 Door	Listed	240304
SC-18	Saddlebag: 2 Door	Listed	240305
SC-19	Saddlebag: 2 Door	Listed	240306
SC-20	Saddlebag: 2 Door	Listed	240308
SC-21	Saddlebag: 2 Door	Listed	240309
SC-22	Saddlebag: 2 Door	Listed	240310
SC-23	Saddlebag: 2 Door	Listed	240312
SC-24	Double Pen	Listed	240313
SC-25	Hall-parlor	Listed	240314
SC-26	Gabled Ell Cottage	Listed	240315
SC-27	Saddlebag: 2 Door	Listed	240317
SC-28	Cross Gable Bungalow	Not Eligible	240249
SC-29	New South Cottage	Not Eligible	240251
SC-30	Ranch House	Not Eligible	240253
SC-31	American Small House	Not Eligible	240255
SC-32	Ranch House	Not Eligible	240256
SC-33	Queen Anne Cottage	Not Eligible	240259
SC-34	Georgian Cottage	Not Eligible	240260
SC-35	Georgian Cottage	Not Eligible	240261
SC-36	Georgian Cottage	Not Eligible	240290
SC-37	Gabled Ell Cottage	Listed	240291
SC-38	Gabled Ell Cottage	Listed	240292
SC-39	Shotgun	Listed	240278
SC-40	Hall-parlor	Listed	240279
SC-41	Saddlebag: 2 Door	Listed	240280
SC-42	Saddlebag: 2 Door	Listed	240281
SC-43	Saddlebag: unknown	Listed	240282
SC-44	Hall-parlor	Listed	240283

ALL IDENTIFIED RESOURCES

Resource ID	Description	NRHP Recommendation	GNARHGIS ID
SC-45	Saddlebag: 2 Door	Listed	240284
SC-46	Hipped Bungalow	Listed	240285
SC-47	Cemetery	Listed	240286
SC-48	Ranch House	Potentially Eligible	240287
SC-49	Ranch House	Potentially Eligible	240288
SC-50	Central Hallway Cottage	Listed	240289
SC-51	Ranch House	Not Eligible	240898
SC-52	Georgian House	Not Eligible	64935
SC-53	Ranch House	Not Eligible	240311
SC-54	Saddlebag: 2 Door	Listed	241005
SC-55	Hall-parlor	Not Eligible	241002
SC-56	Saddlebag: 2 Door	Not Eligible	65119
SC-57	Georgian Cottage	Potentially Eligible	240316
SC-58	Pyramid Cottage	Not Eligible	240318
SC-59	Other	Not Eligible	240358
SC-60	Ranch House	Not Eligible	240904
SC-61	Cross Gable Bungalow	Not Eligible	240359
SC-62	Ranch House	Not Eligible	240361
SC-63	New South Cottage	Not Eligible	240362
SC-64	Front Gable Bungalow	Not Eligible	240363
SC-65	Side Gable Bungalow	Not Eligible	240905
SC-66	Side Gable Bungalow	Potentially Eligible	240906
SC-67	Ranch House	Not Eligible	240907
SC-68	Ranch House	Not Eligible	240448
SC-69	Ranch House	Not Eligible	240449
SC-70	Ranch House	Not Eligible	240450
SC-71	Connor Family Cemetery	Potentially Eligible	240451
SC-72	Ranch House	Potentially Eligible	240454
SC-73	Ranch House	Not Eligible	240455
SC-74	Front Gable Bungalow	Listed	65144
SC-75	Mars Hill Baptist Church	Listed	240616
SC-76	Gabled Ell Cottage	Listed	240617
SC-77	Georgian House	Listed	240656
SC-78	Georgian House	Listed	240662
SC-79	Georgian House	Listed	240665
SC-80	Queen Anne House	Listed	240668
SC-81	Queen Anne Cottage	Listed	240669
SC-82	Hall-parlor	Listed	240685
SC-83	English Cottage	Listed	240686
SC-84	English Cottage	Listed	240687
SC-85	Side Gable Bungalow	Potentially Eligible	240270
SC-86	Side Gable Bungalow	Not Eligible	240271
SC-87	New South Cottage	Potentially Eligible	64924
SC-88	Duplex	Not Eligible	240272

		NRHP	GNARHGIS
Resource ID	Description	Recommendation	ID
SC-89	Ranch House	Not Eligible	240274
SC-90	Central Hallway Cottage	Not Eligible	240275
SC-91	American Small House	Listed	240908
SC-92	Single Retail Commercial Structure	Listed	64933
SC-93	Single Retail Commercial Structure	Not Eligible	240909
SC-94	Multiple Retail Commercial Block	Listed	64932
SC-95	Multiple Retail Commercial Block	Listed	64931
SC-96	Multiple Retail Commercial Block	Listed	64930
SC-97	Single Retail Commercial Structure	Listed	64929
SC-98	Multiple Retail Commercial Block	Listed	64928
SC-99	Multiple Retail Commercial Block	Listed	64927
SC-100	Multiple Retail Commercial Block	Listed	240371
SC-101	Multiple Retail Commercial Block	Listed	64926
SC-102	Circle View Cemetery	Potentially Eligible	240372
SC-103	Ranch House	Not Eligible	240910
SC-104	Queen Anne House	Listed	241004
SC-105	Georgian House	Potentially Eligible	65143
SC-106	Ranch House	Not Eligible	240911
SC-107	Ranch House	Listed	240432
SC-108	Saddlebag: 2 Door	Listed	64939
SC-109	Ranch House	Not Eligible	240433
SC-110	Ranch House	Not Eligible	240434
SC-111	Ranch House	Not Eligible	240435
SC-112	Side Gable Bungalow	Not Eligible	240436
SC-113	New South Cottage	Not Eligible	64962
SC-114	Hipped Bungalow	Not Eligible	240437
SC-115	Unknown	Listed	240457
SC-116	Georgian Cottage	Listed	240460
SC-117	Georgian House	Listed	240462
SC-118	Queen Anne Cottage	Listed	240464
SC-119	Side Gable Bungalow	Listed	240935
SC-120	New South Cottage	Listed	240466
SC-121	Cross Gable Bungalow	Listed	65154
SC-122	Queen Anne Cottage	Listed	240467
SC-123	Side Gable Bungalow	Not Eligible	240378
SC-124	Front Gable Bungalow	Not Eligible	240380
SC-125	American Small House	Not Eligible	240382
SC-126	Ranch House	Not Eligible	240944
SC-127	Ranch House	Not Eligible	240385
SC-128	Hipped Bungalow	Not Eligible	240393
SC-129	Gabled Ell Cottage	Not Eligible	240395
SC-130	Ranch House	Not Eligible	240397
SC-131	Ranch House	Not Eligible	240398
SC-132	Ranch House	Not Eligible	240401

ALL IDENTIFIED RESOURCES

Resource ID	Description	NRHP Recommendation	GNARHGIS ID
SC-133	Ranch House	Not Eligible	240402
SC-134	Ranch House	Not Eligible	240403
SC-135	Ranch House	Not Eligible	240404
SC-136	Ranch House	Not Eligible	240405
SC-137	Ranch House	Not Eligible	240406
SC-138	Ranch House	Not Eligible	240407
SC-139	Ranch House	Not Eligible	240408
SC-140	Ranch House	Not Eligible	204409
SC-141	Ranch House	Not Eligible	240410
SC-142	Ranch House	Not Eligible	240412
SC-143	Ranch House	Not Eligible	240413
SC-144	Georgian House	Listed	64952
SC-145	Queen Anne Cottage	Potentially Eligible	240414
SC-146	Commercial: Motel	Not Eligible	240415
SC-147	Social Circle United Methodist	Listed	240416
SC-148	Gas Station	Not Eligible	240424
SC-149	Ranch House	Not Eligible	240425
SC-150	Ranch House	Not Eligible	240426
SC-151	Ranch House	Not Eligible	240427
SC-152	Ranch House	Not Eligible	240428
SC-153	Georgian House	Not Eligible	240429
SC-154	Georgian House	Not Eligible	240230
SC-155	Ranch House	Not Eligible	240438
SC-156	Ranch House	Not Eligible	240439
SC-157	Ranch House	Not Eligible	240440
SC-158	Ranch House	Not Eligible	240441
SC-159	English Cottage	Listed	240442
SC-160	Georgian House	Listed	65153
SC-161	Queen Anne Cottage	Listed	65155
SC-162	Cross Gable Bungalow	Not Eligible	240982
SC-163	Queen Anne Cottage	Listed	65161
SC-164	Gas Station	Not Eligible	240245
SC-165	Georgian House	Listed	240246
SC-166	Georgian Cottage	Listed	240248
SC-167	Double Tower Church	Listed	240252
SC-168	Georgian Cottage	Listed	65131
SC-169	English Cottage	Listed	65132
SC-170	New South Cottage	Listed	65133
SC-171	Georgian House	Listed	65134
SC-172	Georgian Cottage	Potentially Eligible	240262
SC-173	Side Gable Bungalow	Listed	65139
SC-174	Georgian House	Listed	65138
SC-175	Georgian House	Listed	240265
SC-176	Gabled Ell Cottage	Listed	65136

ALL IDENTIFIED RESOURCES DATA

Resource ID	Description	NRHP Recommendation	GNARHGIS ID
SC-177	Queen Anne Cottage	Listed	65135
SC-178	Saddlebag: Central Door	Not Eligible	240268
SC-179	Central Hallway Cottage	Potentially Eligible	65117
SC-180	Shotgun	Listed	240379
SC-181	Single Retail Commercial Structure	Not Eligible	240381
SC-182	New South Cottage	Listed	240383
SC-183	Great Walton Railroad Office	Listed	240386
SC-184	Single Retail Commercial Structure	Not Eligible	240387
SC-185	Queen Anne Cottage	Listed	240390
SC-186	Georgian Cottage	Listed	240391
SC-187	Gabled Ell Cottage	Not Eligible	240392
SC-188	Gabled Ell Cottage	Listed	240394
SC-189	Cross Gable Bungalow	Potentially Eligible	240396
SC-190	Queen Anne Cottage	Potentially Eligible	240399
SC-191	Ranch House	Not Eligible	240912
SC-192	American Small House	Potentially Eligible	240400
SC-193	Ranch House	Potentially Eligible	240417
SC-194	Side Gable Bungalow	Not Eligible	240418
SC-195	Central Hallway Cottage	Potentially Eligible	240419
SC-196	Georgian cottage	Listed	240420
SC-197	Georgian Cottage	Listed	240421
SC-198	Cross Gable Bungalow	Listed	240422
SC-199	Central Hallway Cottage	Listed	240423
SC-200	Queen Anne Cottage	Potentially Eligible	240502
SC-201	Front Gable Bungalow	Not Eligible	240503
SC-202	New South Cottage	Not Eligible	64934
SC-203	Ranch House	Not Eligible	240504
SC-204	Ranch House	Not Eligible	240505
SC-205	Side Gable Bungalow	Not Eligible	240518
SC-206	Ranch House	Not Eligible	240519
SC-207	Ranch House	Not Eligible	240521
SC-208	Ranch House	Not Eligible	240522
SC-209	Ranch House	Not Eligible	240523
SC-210	Ranch House	Not Eligible	240524
SC-211	Ranch House	Not Eligible	240525
SC-212	Ranch House	Not Eligible	240527
SC-213	Cemetery	Not Eligible	240536
SC-214	Front Gable Bungalow	Not Eligible	240538
SC-215	Front Gable Bungalow	Not Eligible	240540
SC-216	Front Gable Bungalow	Not Eligible	240542
SC-217	Front Gable Bungalow	Not Eligible	240545
SC-218	Front Gable Bungalow	Not Eligible	240549
SC-219	Front Gable Bungalow	Not Eligible	240564
SC-220	American Small House	Not Eligible	240550
		0	1-00-

ALL IDENTIFIED RESOURCES

Resource ID	Description	NRHP Recommendation	GNARHGIS ID
SC-221	Ranch House	Not Eligible	240562
SC-222	Multiple Retail Commercial Block	Listed	240567
SC-223	Multiple Retail Commercial Block	Listed	65145
SC-224	Multiple Retail Commercial Block	Listed	240584
SC-225	Multiple Retail Commercial Block	Listed	240585
SC-226	Multiple Retail Commercial Block	Listed	240586
SC-227	Multiple Retail Commercial Block	Listed	240587
SC-228	Multiple Retail Commercial Block	Listed	65148
SC-229	American Small House	Not Eligible	240588
SC-230	Cross Gable Bungalow	Listed	2403 77
SC-231	Side Gable Bungalow	Not Eligible	240590
SC-232	double pen	Not Eligible	240591
SC-233	Cross Gable Bungalow	Not Eligible	240607
SC-234	Ranch House	Not Eligible	240609
SC-235	Ranch House	Not Eligible	240610
SC-236	American Small House	Not Eligible	240611
SC-237	Ranch House	Not Eligible	240612
SC-238	Cross Gable Bungalow	Not Eligible	240618
SC-239	Gabled Ell Cottage	Potentially Eligible	240619
SC-240	Side Gable Bungalow	Not Eligible	240620
SC-241	Ranch House	Potentially Eligible	240621
SC-242	Georgian cottage	Not Eligible	240623
SC-243	Front Gable Bungalow	Not Eligible	240622
SC-244	American Small House	Not Eligible	240624
SC-245	American Small House	Not Eligible	240625
SC-246	Cross Gable Bungalow	Listed	65159
SC-247	Ranch House	Not Eligible	240627
SC-248	Ranch House	Not Eligible	240628
SC-249	Queen Anne Cottage	Listed	65168
SC-250	Side Gable Bungalow	Listed	240608
SC-251	Gabled Ell Cottage	Listed	240613
SC-252	Gabled Ell Cottage	Listed	240614
SC-253	Ranch House	Not Eligible	240615
SC-254	Ranch House	Not Eligible	240629
SC-255	Ranch House	Not Eligible	240630
SC-256	Ranch House	Not Eligible	240631
SC-257	Ranch House	Potentially Eligible	240635
SC-258	Ranch House	Not Eligible	240637
SC-259	Ranch House	Not Eligible	240639
SC-260	Hipped Bungalow	Not Eligible	240641
SC-261	Gabled Ell Cottage	Potentially Eligible	240642
SC-262	Ranch House	Not Eligible	240644
SC-263	Ranch House	Not Eligible	240645
SC-264	Ranch House	Not Eligible	240646

ALL IDENTIFIED RESOURCES DATA

Resource ID	Description	NRHP Recommendation	GNARHGIS ID
SC-265	Ranch House	Not Eligible	240647
SC-266	Ranch House	Not Eligible	240648
SC-267	Ranch House	Potentially Eligible	240649
SC-268	Cemetery	Eligible	240663
SC-269	Ranch House	Not Eligible	240468
SC-270	American Small House	Not Eligible	240469
SC-271	Ranch House	Potentially Eligible	240915
SC-272	Ranch House	Not Eligible	240470
SC-273	Ranch House	Potentially Eligible	240471
SC-274	Ranch House	Potentially Eligible	240472
SC-275	Ranch House	Not Eligible	240473
SC-276	Ranch House	Potentially Eligible	240474
SC-277	Ranch House	Not Eligible	240475
SC-278	Side Gable Bungalow	Listed	240376
SC-279	Ranch House	Not Eligible	240477
SC-280	Ranch House	Not Eligible	240479
SC-281	Side Gable Bungalow	Potentially Eligible	65098
SC-282	Gabled Ell Cottage	Not Eligible	240481
SC-283	Side Gable Bungalow	Not Eligible	240916
SC-284	Side Gable Bungalow	Not Eligible	240917
SC-285	Ranch House	Not Eligible	240919
SC-286	Front Gable Bungalow	Not Eligible	240920
SC-287	Central Hallway Cottage	Not Eligible	240921
SC-288	Ranch House	Not Eligible	240913
SC-289	Front Gable Bungalow	Not Eligible	240914
SC-290	Single Pen	Eligible	240918
SC-291	Ranch House	Not Eligible	240922
SC-292	Single Pen	Not Eligible	240923
SC-293	Single Pen	Eligible	240924
SC-294	Single Pen	Not Eligible	240925
SC-295	Ranch House	Not Eligible	240926
SC-296	Ranch House	Not Eligible	240927
SC-297	Ranch House	Not Eligible	240928
SC-298	Ranch House	Not Eligible	240929
SC-299	Ranch House	Not Eligible	240930
SC-300	Queen Anne Cottage	Listed	65141
SC-301	Queen Anne House	Listed	240326
SC-302	Queen Anne Cottage	Listed	240327
SC-303	New South Cottage	Listed	240328
SC-304	Ranch House	Not Eligible	240329
SC-305	Georgian House	Listed	240330
SC-306	Georgian House	Listed	240344
SC-307	Cross Gable Bungalow	Listed	240336
SC-308	Side Gable Bungalow	Listed	240338

ALL IDENTIFIED RESOURCES

Resource ID	Description	NRHP Recommendation	GNARHGIS ID
SC-309	Queen Anne Cottage	Listed	240340
SC-310	Georgian House	Listed	240342
SC-311	Georgian Cottage	Listed	240343
SC-312	New South Cottage	Listed	240344
SC-313	Front Gable Bungalow	Listed	240347
SC-314	Cross Gable Bungalow	Listed	240348
SC-315	New South Cottage	Listed	240349
SC-316	New South Cottage	Listed	240350
SC-317	Side Gable Bungalow	Not Eligible	240351
SC-318	Central Hallway Cottage	Potentially Eligible	240352
SC-319	Central Hallway Cottage	Potentially Eligible	240353
SC-320	Gabled Ell Cottage	Not Eligible	240950
SC-321	Ranch House	Not Eligible	240931
SC-322	Single Retail Commercial Structure	Listed	240375
SC-323	Side Gable Bungalow	Not Eligible	240557
SC-324	Ranch House	Not Eligible	240558
SC-325	Side Gable Bungalow	Potentially Eligible	240559
SC-326	American Small House	Potentially Eligible	240560
SC-327	Single Retail Commercial Structure	Not Eligible	240561
SC-328	Front Gable Bungalow	Not Eligible	240563
SC-329	Front Gable Bungalow	Not Eligible	240593
SC-330	Ranch House	Not Eligible	240595
SC-331	Gabled Ell Cottage	Not Eligible	65094
SC-332	Side Gable Bungalow	Not Eligible	240597
SC-333	English Cottage	Not Eligible	65095
SC-334	Ranch House	Not Eligible	240598
SC-335	Multiple Retail Commercial Block	Listed	240599
SC-336	Multiple Retail Commercial Block	Listed	240600
SC-337	Multiple Retail Commercial Block	Listed	240601
SC-338	Multiple Retail Commercial Block	Listed	240602
SC-339	Multiple Retail Commercial Block	Listed	240603
SC-340	Multiple Retail Commercial Block	Listed	240604
SC-341	Multiple Retail Commercial Block	Listed	240605
SC-342	Multiple Retail Commercial Block	Listed	240932
SC-343	Multiple Retail Commercial Block	Listed Listed	240606
SC-344	Multiple Retail Commercial Block		240933
SC-345	Ranch House	Not Eligible Listed	240431
SC-346	Front Gable Bungalow Front Gable Bungalow	Listed	240354
SC-347 SC-348	American Small House	Not Eligible	240355
SC-348 SC-349	Front Gable Bungalow	Listed	240356
SC-349 SC-350	Front Gable Bungalow Front Gable Bungalow	Listed	240357 240360
SC-350 SC-351	Front Gable Bungalow	Listed	240300
SC-351 SC-352	Georgian Cottage	Listed	2403/3 240374
50-392	ovorgian oottage	Listu	- 403/4

DATA


Resource ID	Description	NRHP Recommendation	GNARHGIS ID
SC-353	Cross Gable Bungalow	Listed	241007
SC-354	Cross Gable Bungalow	Potentially Eligible	240589
SC-355	Side Gable Bungalow	Listed	65128
SC-356	Side Gable Bungalow	Listed	242524
SC-357	Hipped Bungalow	Listed	65127
SC-358	School building: multi-wing	Not Eligible	242525
SC-359	Queen Anne Cottage	Listed	65144
SC-360	Queen Anne House	Listed	65125
SC-361	Queen Anne House	Listed	65124
SC-362	Side Hallway	Listed	65123
SC-363	Side Hallway	Listed	65122
SC-364	Queen Anne Cottage	Listed	242535
SC-365	Georgian Cottage	Listed	242536
SC-366	Side Gable Bungalow	Listed	242537
SC-367	Queen Anne Cottage	Listed	242538
SC-368	Saddlebag: 2 Door	Listed	242539
SC-369	Saddlebag: 2 Door	Listed	242540
SC-370	I-house	Listed	242541

Use

Civic

Table 1. Field Survey Results, Description of all Identified Resources


RESOURCES: CURRENT USE



#

1

RESOURCES: CURRENT USE PERCENT-AGES



Use	%
Civic	0.3%
Commercial: Single Retail	9%
Educational: School	1%
Funerary: Cemetery	2%
Governmental: Post Office	0.3%
Religious: Church	1%
Residential: Multiple Family Dwelling	1%
Residential: Single Family Dwelling	83%
Transportation: Depot	0.3%
Vacant	4%

Table 3. Field Survey Results, All Identified Resources, Use Percentages

RESOURCES: AGE DISTRIBUTION

Age	Count	
1840-1849	2	
1850-1859	1	
1860-1869	3	
1865-1874	1	
1870-1879	3	
1875-1884	1	
1880-1889	8	
1885-1894	10	
1890-1899	9	
1895-1904	5	
1900-1909	25	
1905-1914	18	
1910-1919	73	
1915-1924	8	
1920-1929	19	
1925-1934	12	
1930-1939	22	
1935-1944	7	
1940-1949	10	
1945-1954	8	
1950-1959	17	
1955-1964	22	
1960-1969	31	
1965-1974	37	
1970-1979	11	
1975-1984	7	
	370	




Table 4. Field Survey Results, All Identified Resources, Age Distribution

ALL IDENTIFIED DATA

RESOURCES: CONSTRUCTION DATE 1940-1949 1935-1944 _3% 1930-1939 1945-1954 1925-1934 2% 6% 2% 1950-1959 1920-1929 3% .5% 5% 1915-1924 1955-1964 2% 6% 1960-1969 8% 1910-1919 20% 1965-1974 10% 1900-1909 7% 1905-1914 1970-1979 5% 3% 1975-1984 1895-1904 1890-1899 1885-1894 2% 1840-1849 1% 1860-2% 3% 1% 1869 1880-1889 1% 1870-2% 1850-1859 1865-1874 1879 1875-1884 0% 0% 1% 0% Age Percent Age Percent 1840-1849 0.5% 1915-1924 2.2% 1850-1859 0.3% 1920-1929 5.1% 1860-1869 0.8% 1925-1934 3.2% 1865-1874 0.3% 1930-1939 5.9% 1870-1879 0.8% 1.9% 1935-1944 1875-1884 0.3% 1940-1949 2.7% 1880-1889 2.2% 1945-1954 2.2% 1885-1894 2.7% 1950-1959 4.6% 1890-1899 2.4% 1955-1964 5.9% 1895-1904 1.4% 1960-1969 8.4%

Table 5. Field Survey Results, All Identified Resources, Construction Date by Percentage

1965-1974

1970-1979

1975-1984

10.0%

3.0%

1.9%

6.8%

4.9%

19.7%


1900-1909

1905-1914

1910-1919

ALL IDENTIFIED DATA

RESOURCES: RESIDENTIAL BUILDING TYPES




Residential House Type	Count	Residential House Type	Count
American Small House	12	Georgian House	17
Cross Gable Bungalow	14	Hall-parlor	5
Front Gable Bungalow	21	I-house	1
Hipped Bungalow	6	New South Cottage	12
Side Gable Bungalow	25	Pyramid Cottage	1
Central Hallway	9	Queen Anne Cottage	18
Double Pen	3	Queen Anne House	5
Double Shotgun	2	Ranch House	100
Duplex	1	Saddlebag	28
English Cottage	5	Shotgun	2
Gabled Ell Cottage	15	Side Hallway	2
Georgian Cottage	15	Single Pen	4
		Total	323

Table 6. Field Survey Results, All Identified Resources, Residential Building Types

ALL IDENTIFIED DATA

RESOURCES: RESIDENTIAL BUILDING TYPE BY %




Residential House Type	Count	Residential House Type	Count
American Small House	3.7%	Georgian House	5.3%
Cross Gable Bungalow	4.3%	Hall-parlor	1.5%
Front Gable Bungalow	6.5%	I-house	0.3%
Hipped Bungalow	1.9%	New South Cottage	3.7%
Side Gable Bungalow	7.7%	Pyramid Cottage	0.3%
Central Hallway	2.8%	Queen Anne Cottage	5.6%
Double Pen	0.9%	Queen Anne House	1.5%
Double Shotgun	0.6%	Ranch House	31.0%
Duplex	0.3%	Saddlebag	8.7%
English Cottage	1.5%	Shotgun	0.6%
Gabled Ell Cottage	4.6%	Side Hallway	0.6%
Georgian Cottage	4.6%	Single Pen	1.2%

Table 7. Field Survey Results, All Identified Resources, Residential Building Type By Percentage


ALL IDENTIFIED DATA

RESOURCES: ARCHITECTURAL STYLES



Style	Count	
Colonial Revival	23	
Craftsman	31	
Early Classical Revival	2	
English Vernacular	5	
Folk Victorian	38	
Greek Revival	3	
Italianate	4	
Moderne	1	
Neoclassical Revival	8	
No Academic Style	238	
Queen Anne	7	
Second Empire	1	
Tudor	2	

Table 8. Field Survey Results, All Identified Resources, Architectural Styles



Style	Percent
Colonial Revival	6.3%
Craftsman	8.5%
Early Classical Revival	0.6%
English Vernacular	1.4%
Folk Victorian	10.5%
Greek Revival	0.8%
Italianate	1.1%
Moderne	0.3%
Neoclassical Revival	2.1%
No Academic Style	65.6%
Queen Anne	1.9%
Second Empire	0.3%
Tudor	0.6%

Table 9. Field Survey Results, All Identified Resources, Architectural Styles by Percentage

Integrity



The condition of most surveyed properties was noted as fair to good, with the majority displaying a medium level of integrity. The integrity of resources can be affected by major non-historic alterations. These changes include additions to the building and material replacements including but not limited to: exterior cladding, porch alterations, window or door replacements, etc. Routine maintenance such as roof repair or repointing was not considered when evaluating architectural integrity.

Resources designated within the Social Circle Historic District overall have maintained excellent architectural integrity. A few instances exist where alterations have diminished the overall integrity of the resource. These resources are noted as 'Not Eligible' for listing in the National Register for Historic Places;' however, they have not been delisted from the original district. The historic district maintains enough architectural integrity to adequately express its historic significance. 13 of the 370 structures (4%) surveyed are currently vacant. Vacant properties are considered highly endangered because they are more susceptible to fire and vandalism. Additionally, repairs and weatherproofing are not carried out in a timely manner, thus leaving structures to decay.

The existing Social Circle Historic District has 148 contirubting properties and is listed as a single district in the National Register

of Historic Places. Of the remaining resources, 8 are considered eligible but not listed within the district, and an additional 35 are potentially eligible for listing in the National Register. These resources were individually evaluated under the appropriate criteria; event, person, design, and information potential, and maintain good to excellent architectural integrity.


















DR. BROWN'S TOWNHOUSE C-1850

Conclusion


The City of Social Circle has done an excellent job maintaining the resources listed in its historic district. The number of intact mid-century resource which maintain high levels of architectural integrity express a period of significant growth in Georgia. Ranch house neighborhoods currently exist and mainly have a fair to good level of integrity; however, they are not excellent examples of mid-century residental planning, nor do they possess high levels of historic significance as outlined in the Georgia Department of Natural Resources, Historic Preservation Division's, "The Ranch House in Georgia: Guidelines for Evaluation." The disparate locations of these resources do not suggest a future Ranch House historic district. Social Circle does not appear to suffer from extreme developmental pressures; the documented Ranch Houses are located in well established neighborhoods. Although few of the resources are potentially eligible for listing in the National Register, none appear to be the work of a significant architect, or possess elements of high style architecture or are exemplary illustrations of this house type.

IDENTIFIED RESOURCES





Social Circle Historic Resource		NARGHIS ID	240250	
Y OF G	Resource ID SC-02		Resource Type	Building
Iandscape architecture	Address 332 Cannon Dr		Resource Use Date of Constru	Residential: Single Family Dwelling
D historic preservation D env. planning + design S E environmental ethics	County Walton		House Type	Saddlebag: 2 Door
			Barn Type	
			Church Type	
			Commercial Typ	pe
			School Type	
	and the second sec		Structural Syste	em Balloon frame
	- HT BAS	<u> </u>	Style No	academic style
			Roof Ga	ble: Side
			Exterior Claddir	ng Wood: Weatherboard
			Foundation Pie	r with infill: brick
			Porch Ver	randah
	de de de		Windows Do	uble hung sash: 2/2
100			Chimney Brid	ck: center
			Alterations Rep	placement windows, rear addition
Preliminary A	ssessment	Status - Listed		Applicable Criteria
Not eli		Listed		C





Social Circle Historic Resource

Resource ID SC-04


Address 354 Cannon Dr

County Walton




NARGHIS ID 240257 Building **Resource Type Resource Use** Residential: Single Family Dwelling Date of Construction 1925-1934 **Double Shotgun House Type** Barn Type **Church Type Commercial Type School Type Balloon frame** Structural System No academic style Style Gable: Front Roof **Exterior Cladding** Wood: Weatherboard Foundation Pier with infill: brick Verandah Porch Double hung sash: 6/6 Windows Center: Brick Chimney Rear shed addition Alterations

Preliminary Assessment	Status - Listed	Applicable Criteria	
Eligible	Listed	С	



	Social Circle Historio	c Resource	NARGHIS ID 240263	
D 10 VIR	Resource ID SC-06		Resource Type Building	
C E + D Indscape architecture Henv.planning + design H environmental ethics	Address 449 Cedar St County Walton		Resource Use Residential: Single Family Dwelling Date of Construction 1910-1919 House Type Double Pen Barn Type	
			Church Type Commercial Type School Type Structural System Balloon Frame Style No academic style Roof Gable: Side	
			Exterior CladdingWood: WeatherboardFoundationUnknownPorchVerandahWindowsDouble Hung Sash: 6/6ChimneyNo Chimney ObservedAlterationsIntegrated carport addition, replacement materials	
Preliminary A Not El		Status - Listed Listed	Applicable Criteria C	





Resource ID SC-08


Address 355 Cedar St

County Walton




NARGHIS ID 240266 **Resource Type** Building **Resource Use** Residential: Single Family Dwelling Date of Construction 1910-1919 Saddlebag: 2 door **House Type** Barn Type **Church Type Commercial Type School Type** Structural System **Balloon Frame** Style No academic style Roof Gable: Side Exterior Cladding Synthetic Siding: vinyl Foundation Pier with infill: brick Porch Verandah Windows Double Hung Sash: 6/6, 9/9 Chimney Center: brick Alterations Multiple rear additions, mid-century awnings

Preliminary Assessment	Status - Listed	Applicable Criteria	
Eligible	Listed	С	



	Social Circle Histori	c Resource	NARGHIS ID 240269
5 40 A	Resource ID SC-10		Resource Type Building
Landscape architecture region bistoric preservation genue planning + design environmental ethics	Address 345 Cedar S County Walton		Resource UseResidential: Single Family DwellingDate of Construction1910-1919House TypeSaddlebag: 2 doorBarn TypeChurch Type
			Commercial TypeSchool TypeStructural SystemBalloon FrameStyleNo academic styleRoofGable: Side
			Exterior CladdingSynthetic Siding: VinylFoundationPier with infill: brickPorchVerandahWindowsDouble Hung Sash: 2/2ChimneyCenter: brickAlterationsMaterial replacements
Preliminary A Not Eli		Status - Listed Listed	Applicable Criteria C





Address 314 Cedar St

Resource ID SC-12

County Walton





NARGHIS ID 240276 **Resource Type** Building **Resource Use** Residential: Single Family Dwelling Date of Construction 1910-1919 Saddlebag: 2 door **House Type** Barn Type **Church Type Commercial Type School Type** Structural System **Balloon Frame** Style No academic style Roof Gable: side **Exterior Cladding** Wood: Weatherboard Foundation Pier with infill: brick Porch Verandah Windows Double hung sash: 9/9 Chimney Center: brick Alterations Rear addition

Preliminary Assessment	Status - Listed	Applicable Criteria	
Eligible	Listed	С	



	Social Circle Historio	c Resource	NARGHIS ID 2	40301		
OF ENVIR	Resource ID SC-14	F	Resource Type	Building		
Landscape architecture + D historic preservation B	Address 294 Cedar S	f I I I I	Resource Use Residential: Single Family Dwelling Date of Construction 1910-1920			
H env. planning + design st	County Walton	E	louse Type S Barn Type Church Type Commercial Type	Saddlebag: 2 door		
		S S F F F F V V C	Roof Gable Exterior Cladding Foundation Pier w Porch Veran Vindows Doubl Chimney Cente	ademic style e: side Synthetic siding: m vith infill: brick	asonite	
Preliminary A		Status - Listed Listed	A	pplicable Criteria C		





Address 269 Cedar St



NARGHIS	NARGHIS ID 240303				
Resource Ty	pe Building				
Resource Us	e Residential: Single Family Dwelling				
Date of Cons	truction ¹⁹¹⁰⁻¹⁹¹⁹				
House Type	Hall-parlor				
Barn Type					
Church Type					
Commercial	Туре				
School Type					
Structural System Balloon Frame					
Style	No academic style				
Roof	Gable: side				
Exterior Clac	Iding Synthetic siding: vinyl				
Foundation	Pier with infill: brick				
Porch	Verandah				
Windows	Double hung sash: 6/6				
Chimney	Center: brick				
Alterations	Replacement materials, addition				

Preliminary Assessment	Status - Listed	Applicable Criteria	
Not Eligible	Listed	С	



Resource ID SC-17

Address 264 Cedar St

County Walton



NARGHIS ID 240304

Building **Resource Type** Residential: Single Family Dwelling **Resource Use** Date of Construction 1910-1919 Saddlebag: 2 door House Type Barn Type **Church Type Commercial Type** School Type **Balloon Frame** Structural System No academic style Style Gable: side Roof Exterior Cladding Wood: weatherboard Foundation Continuous: brick Porch Verandah Double hung sash: 6/6, 2/2 Windows Center: brick Chimney Replacement materials, addition Alterations

Preliminary Assessment Eligible Status - Listed Listed

Applicable Criteria C

	Social Circle Historic Resource	NARGHIS ID 240305
Y OF G	Resource ID SC-18	Resource Type Building
C E+D Handscape architecture historic preservation pr g env. planning + design	Address 250 Cedar St County Walton	Resource UseResidential: Single Family DwellingDate of Construction1910-1919House TypeSaddlebag: 2 door
F environmental ethics 2	County Walton	House TypeSaddlebag: 2 doorBarn TypeChurch TypeCommercial TypeSchool TypeStructural SystemBalloon FrameStyleNo academic styleRoofGable: sideExterior CladdingSynthetic siding: vinylFoundationPier with infill: brick
		Porch Verandah Windows Double hung sash: 6/6, 9/9
a friend		ChimneyCenter: stuccoed masonryAlterationsReplacement materials, addition

 Preliminary Assessment
 Status - Listed
 Applicable Criteria

 Eligible
 Listed
 C





Resource ID SC-20


Address 240 Cedar St

County Walton




NARGHIS	^{ID} 240308
Resource Ty	pe Building
Resource Us	e Residential: Single Family Dwelling
Date of Cons	struction 1910-1919
House Type	Saddlebag: 2 door
Barn Type	
Church Type	
Commercial	Туре
School Type	
Structural Sy	stem Balloon Frame
Style	No academic style
Roof	Gable: side
Exterior Clac	Iding Synthetic siding: vinyl
Foundation	Pier with infill: brick
Porch	Verandah
Windows	Double hung: 6/6
Chimney	No chimney observed
Alterations	Replacement materials

Preliminary Assessment	Status - Listed	Applicable Criteria	
Not eligible	Listed	С	




GE ORGIA	Social Circle Histo	oric Resource	NARGHIS ID 240310		
7 OF G	Resource ID SC-22		Resource Type Building		
Andscape architectur historic preservatio env. planning + desig environmental ethic	Address 224 Canno County Walton	on Dr	Resource UseResidential: Single Family DwellingDate of Construction1910-1919House TypeSaddlebag: 2 door		
		12885-8	Barn Type Church Type		
	1	and the second	Commercial Type		
Eliter .			School Type		
	A GI	A A A A A A A A A A A A A A A A A A A	Structural System Balloon Frame		
			Style No academic style		
			Roof Gable: Side		
7.00			Exterior Cladding Synthetic siding: vinyl		
1 President			Foundation Unknown		
3000			Porch Verandah		
1 gray	and the second sec	The second second	Windows Double Hung sash: 6/6		
18.2°		100 miles	Chimney Center: brick		
1			Alterations Replacement materials: door, siding, porch supports; rear addition		
	ry Assessment	Status - Listed	Applicable Criteria		
	Eligible	Listed	C		






NARGHIS	NARGHIS ID 240313				
Resource Ty	pe Building				
Resource Us	e Residential: Single Family Dwelling				
Date of Cons	truction ¹⁹¹⁰⁻¹⁹¹⁹				
House Type	Double pen				
Barn Type					
Church Type					
Commercial	Туре				
School Type					
Structural Sy	vstem Balloon Frame				
Style	No academic style				
Roof	Gable: side				
Exterior Clac	Iding Synthetic siding: vinyl				
Foundation	Continuous: brick				
Porch	Verandah				
Windows	Double hung sash: 1/1				
Chimney	No chimney observed				
Alterations	Replacement materials, additions				

Preliminary Assessment	Status - Listed	Applicable Criteria	
Eligible	Listed	С	




	Social Circle Histori	ic Resource	NARGHIS ID 240315
OF ENVIR	Resource ID SC-26	F	Resource Type Building
Bandiacape architecture Henv.planning + design environmental ethics	Address 258 Cannon Dr County Walton		Resource Use Residential: Single Family Dwelling Date of Construction 1910-1919 House Type Gabled ell Cottage
			Barn Type Church Type Commercial Type
			School Type Structural System Balloon frame
			Style Folk Victorian
			Roof Gable: cross
			Exterior Cladding Synthetic siding: vinyl Foundation Continuous: brick
		and the second second	Porch Verandah
		N N N N	Windows Double Hung sash: 1/1
			Chimney Off-center ridgeline: brick
			Alterations Replacement siding, non-historic additions
Preliminary A		Status - Listed Listed	Applicable Criteria C



	Social Circle Historio	c Resource	IARGHIS ID 2	40249
OF ENVIR	Resource ID SC-28	R	esource Type	Building
Landscape architecture	Address 673 St Route	11 Couth	esource Use ate of Construct	Residential: Single Family Dwelling
 D historic preservation <l< td=""><td>County Walton</td><td></td><td></td><td>Bungalow: cross gable</td></l<>	County Walton			Bungalow: cross gable
		B	arn Type	
a desta	Charles A. 24	C C	hurch Type	
	Carlor en el	C	ommercial Type	
		S	chool Type	
		S	tructural System	Post and Beam
		S	tyle No a	cademic style
		R	coof Gable	e: cross
			xterior Cladding	Brick: veneer, aluminum
		F	oundation Unkn	iown
		P	orch Stoop	o
		v 🚺 🚺	Vindows Doub	ole hung sash: 6/6
and the second second		C	himney Cente	er: brick
	and the second	A	Iterations Replace	cement siding
_				
Preliminary A		Status - Listed	A	pplicable Criteria
Not eli	gible	Not listed		C



	Social Circle Historio	Resource	NARGHIS ID 240253
9 JO AL	Resource ID SC-30	R	Resource Type Building
Landscape architecture	Address 635 State Ro		Resource Use Residential: Single Family Dwelling Date of Construction 1955-1964
D historic preservation D H env. planning + design SC H environmental ethics S	County Walton		louse Type Ranch
and the state of t			Barn Type
			Church Type Commercial Type
			School Type
		S	Structural System Balloon frame
		S	Style No academic style
		R	Roof Gable: side
		E	xterior Cladding Brick: veneer, aluminum
	and the state of the second	F	oundation Continuous: concrete, brick veneer
29 - C - C - C - C - C - C - C - C - C -		P	Porch Verandah
		V States V	Vindows Double hung sash: 2/2
		C	Chimney Off center within roof surface: brick
Stand Street		A	Alterations
Preliminary A	ssessment	Status - Listed	Applicable Criteria
Not Eli		Not listed	с




Resource Type Building **Resource Use** Educational: school Date of Construction 1955-1964 Ranch **House Type Church Type Commercial Type School Type** Structural System Balloon frame No academic style Hip **Exterior Cladding** Vertical Board, Brick Foundation Pier with infill: brick Recessed Double hung sash: 2/2 Chimney No chimney observed Alterations Side addition, enclosed carport


 Preliminary Assessment
 Status - Listed
 Applicable Criteria

 Not eligible
 Not listed
 C

C E⁺D



	Social Circle Historic	Resource	NARGHIS ID	9 240260
· · · · · · · · · · · · · · · · · · ·	Resource ID SC-34	I	Resource Type	e Building
C E + D ONNERT	Address 434 State Ro		Resource Use Date of Constr	Residential: Single Family Dwelling ruction 1910-1919
Henvironmental ethics	County Walton		House Type	Georgian cottage
			Barn Type Church Type Commercial Ty School Type	уре
			Roof H Exterior Cladd Foundation P	Folk victorian lip ling Wood: weatherboard, drop siding Pier with infill: brick
			Windows D Chimney C	Vrap-around Double hung sash: 6/6 Dff center within roof surface: brick Rear addition
Preliminary Asso Not eligibl		Status - Listed Not listed		Applicable Criteria C





Social Circle Historic Resource Resource ID SC-36

Address 392 State Route 11

County Walton




Building **Resource Type Resource Use** Vacant Date of Construction 1915-1924 Georgian cottage **House Type** Barn Type **Church Type Commercial Type School Type** Structural System Balloon frame Style No academic style


NARGHIS ID 240290


Roof Hip **Exterior Cladding** Synthetic siding: vinyl Foundation Pier with infill: brick Porch Verandah Windows Double hung sash: 4/4, 6/6 Chimney Off center within roof surface Alterations

Replacement materials

Preliminary Assessment	Status - Listed	Applicable Criteria	
Not eligible	Not listed	С	









Social Circle Historic Resource Resource ID SC-40

Address 160 Laurel Dr

County Walton



NARGHIS ID 240279 **Resource Type** Building **Resource Use** Residential: Single Family Dwelling Date of Construction 1915-1924 Hall-parlor **House Type** Barn Type **Church Type Commercial Type School Type** Structural System Balloon frame Style No academic style Roof Gable: side **Exterior Cladding** Wood: weatherboard Foundation Pier with infill: brick Porch Verandah Windows Double hung sash: 9/9 Chimney Off-center within roof surface: brick Alterations Replacement materials, addition

Preliminary Assessment	Status - Listed	Applicable Criteria	
Eligible	Listed	С	



	Social Circle Histori	c Resource	NARGHIS ID 240281
Y OF G	Resource ID SC-42		Resource Type Building
Ladvase architecture design	Address 165 Laurel D		Resource UseResidential: Single Family DwellingDate of Construction1910-1919House TypeSaddlebag: 2 doorBarn TypeChurch TypeChurch TypeCommercial TypeCommercial TypeSchool TypeStructural SystemBalloon frameStyleNo academic styleRoofGable: sideExterior CladdingSynthetic siding: asbestosFoundationPier with infill: brickPorchVerandahWindowsDouble hung sash: 6/6ChimneyOff-center within roof surface: brickAlterationsReplacement materials, addition
	y Assessment ligible	Status - Listed Listed	Applicable Criteria C





Social Circle Historic Resource Resource ID SC-44


Address 186 Laurel Dr

County Walton




NARGHIS ID 240283 **Resource Type** Building **Resource Use** Residential: Single Family Dwelling Date of Construction 1910-1919 Hall-parlor **House Type** Barn Type **Church Type Commercial Type School Type** Structural System Balloon frame Style No academic style Roof Gable: side **Exterior Cladding** Synthetic siding: asbestos Foundation Pier with infill: brick Porch Verandah Windows Double hung sash: 6/6 Chimney Center: brick Alterations Replacement materials

Preliminary Assessment	Status - Listed	Applicable Criteria
Eligible	Listed	С



	Social Circle Historio	c Resource	NARGHIS ID 240285
0 40 AL	Resource ID SC-46		Resource Type Building
Autoropy of the second	Address 191 Laurel D county Walton)r	Resource Use Residential: Single Family Dwelling Date of Construction 1910-1919 House Type Bungalow: hip Barn Type Church Type Church Type Commercial Type School Type Structural System Balloon frame Style No academic style Roof Hip Exterior Cladding Synthetic siding: vinyl Foundation Pier with infill: brick Porch Verandah Windows Double hung sash: 6/6, 1/1
			Chimney Center: brick Alterations Replacement materials
Preliminary A Eligit		Status - Listed Listed	Applicable Criteria C





Resource ID SC-48

Address Approximately 314 A P Henderson Dr


County Walton




NARGHIS ID 240287


Building **Resource Type Resource Use** Residential: Single Family Dwelling Date of Construction 1955-1964 Ranch **House Type** Barn Type **Church Type Commercial Type School Type** Structural System Balloon frame Style No academic style Roof Hip **Exterior Cladding** Brick: common Foundation Unknown Porch Recessed Windows Double hung sash: 2/2 Chimney No chimney observed Alterations Replacement materials

Preliminary Assessment	Status - Listed	Applicable Criteria	
Potentially Eligible	Not listed	С	



	Social Circle Historic	Resource	NARGHIS ID 240287
D 10 VIR	Resource ID SC-50	F	Resource Type Building
historic preservation env.planning + design env.planning + design	Address 213 Cannon S County Walton	St c	Resource Use Residential: Single Family Dwelling Date of Construction 1910-1919 House Type Central Hallway
			Barn Type Church Type Commercial Type School Type
		s	Structural System Balloon frame Style No academic style Roof Gable: side
		F	Exterior Cladding Synthetic siding: vinyl Foundation Unknown
			Porch Verandah Windows Double hung: 2/2
			Chimney Off-center ridgeline: brick Alterations Replacement materials, addition
Preliminary A Eligi		Status - Listed Listed	Applicable Criteria C





Resource ID SC-52 Gunter Hall

Address 425 W Hightower Tr


County Walton



NARGHIS ID 64935 Building **Resource Type Resource Use** Social/Civic: Civic Club Date of Construction 1875-1884 Georgian House **House Type** Barn Type **Church Type Commercial Type School Type** Structural System Balloon frame Italianate Style Roof Hip **Exterior Cladding** Wood: weatherboard

Foundation Brick Porch Verandah Windows Double hung sash: 6/9, 6/6 Chimney Both interior ends: brick Alterations

Preliminary Assessment	Status - Listed	Applicable Criteria
Eligible	Listed	С



OF GEORGIA	Social Circle Histori	c Resource	NARGHIS ID 241005
OF ENVIR	Resource ID SC-54		Resource Type Building
CE+D Indiscape architecture thistoric preservation	Address 264 Cannon	St	Resource UseResidential: Single Family DwellingDate of Construction1910-1919
env planning + design Si environmental ethics S	County Walton		House Type Saddlebag: 2 Door Barn Type Church Type
	el Annes		Commercial Type School Type
			Structural System Balloon frame Style No academic style Roof Gable: side
			Exterior CladdingSynthetic siding: vinylFoundationPier with infill: BrickPorchVerandah
			WindowsDouble hung sash: 1/1ChimneyNo chimney observedAlterationsChimney removed, replacement materials
Preliminary A Not El		Status - Listed Listed	Applicable Criteria C





Resource ID SC-56


Address 1242 West Hightower Tr

County Walton




NARGHIS ID 65119 Building **Resource Type Resource Use** Residential: Single Family Dwelling Date of Construction 1910-1919 Saddlebag: 2 door **House Type** Barn Type **Church Type Commercial Type School Type** Structural System Balloon frame Style No academic style Roof Gable: cross **Exterior Cladding** Wood: board-and-batten Foundation Unknown Porch Verandah Windows Double hung sash: 6/6 Chimney Off-center ridgeline: brick Alterations Multiple additions

Preliminary Assessment	Status - Listed	Applicable Criteria	
Not Eligible	Not Listed	C	




	Social Circle Historic	Resource	NARGHIS ID 24	40318
OF ENVIR	Resource ID SC-58		Resource Type B	uilding
Andread Andrea	Address 1188 West Hi County Walton	ghtower Tr	Date of Constructio	acant n 1930-1939 yramidal Cottage
			RoofHipExterior CladdingFoundationBrickPorchVerandWindowsObscur	
Preliminary A Potentially		Status - Listed Not listed	Ар	plicable Criteria C





Building Residential: Single Family Dwelling Date of Construction 1955-1964 Post-and-beam No academic style Veneer: brick Foundation Continuous: brick Double hung sash: 2/2 No chimney observed

Preliminary Assessment	Status - Listed	Applicable Criteria	
Not Eligible	Not Listed	С	



	Social Circle Historic	Resource	NARGHIS ID 240361
D FENNIR	Resource ID SC-62		Resource Type Building
Landscape architecture	Address 92 West High	tower Tr	Resource UseResidential: Single Family DwellingDate of Construction1965-1974
 historic preservation Henv. planning + design environmental ethics 	County Walton		House Type Ranch
			Barn Type
			Church Type
			Commercial Type School Type
			Structural System Post and Beam Wood
			Style No academic style
		H Siller	Roof Gable: stepped
			Exterior Cladding Wood: weatherboard
The second se	A REAL PROPERTY AND A REAL		Foundation Continuous: brick Porch Verandah
			Windows Double hung sash: 6/6
			Chimney No chimney observed
			Alterations Replacement materials
Preliminary A	Assessment	Status - Listed	Applicable Criteria
Not eli	gible	Not listed	С

OF GEORGIA	Social Circle Historic	Resource	NARGHIS ID 240362
	Resource ID SC-63 Address 92 West High County Walton	ntower Tr	Resource Type Building Resource Use Residential: Single Family Dwelling Date of Construction 1905-1914 House Type New South Cottage Barn Type New South Cottage Church Type Commercial Type School Type Balloon frame Structural System Balloon frame Style No academic style Roof Hip Exterior Cladding Wood: shiplap: Synthetic siding: permastone Foundation Unknown Porch Verandah: front Windows Double hung sash: 6/6 Chimney Off center within roof surface: brick Replacement materials Point materials
Preliminary A Not eli		Status - Listed Not listed	Applicable Criteria C



Resource ID SC-64


Address 92 West Hightower Rd

County Walton



NARGHIS ID 240363 Building **Resource Type Resource Use** Residential: Single Family Dwelling Date of Construction 1930-1939 Bungalow: front House Type Barn Type Church Type **Commercial Type** School Type Structural System Balloon frame Style No academic style Roof Gable: front **Exterior Cladding** Wood: plywood, Concrete block Foundation Brick Porch Portico Windows Double hung sash: 1/1, Fixed 6 pane Chimney No chimney observed Alterations Replacement materials

Preliminary Assessment	Status - Listed	Applicable Criteria	
Not eligible	Not listed	С	



	Social Circle Histori	c Resource	NARGHIS ID 240906
7 OF G	Resource ID SC-66		Resource Type Building
andscape architecture	Address 1515 Cherok	kee Rd	Resource UseResidential: Single Family DwellingDate of Construction1925-1934
environmental ethics et	County Walton		House TypeBungalow: side gableBarn TypeChurch TypeChurch TypeCommercial TypeSchool TypeSchool TypeStructural SystemBalloon frameStyleCraftsmarRoofGable: sideExterior ClatingWood: weatherboardFoundationPier with infill: concretePorchPortico: frontWindowsOutble hung: 6/6Chimney
			Alterations Rear addition
Preliminary A Potentially		Status - Listed Not listed	Applicable Criteria C




Address 1526 N Cherokee Rd

County Walton




Resource Use Residential: Single Family Dwelling Date of Construction 1970-1979 Ranch **House Type** Barn Type **Church Type Commercial Type School Type** Post-and-Beam Structural System Style No academic style Roof Hip **Exterior Cladding** Brick: running bond Foundation Continuous: brick Porch Recessed: front Windows Double hung sash: 6/6 Chimney No chimney observed Alterations

Preliminary Assessment	Status - Listed	Applicable Criteria	
Not eligible	Not listed	С	



	Social Circle Historic	Resource	NARGHIS I	▷ 240450
Address of the second s	Resource ID SC-70 Bar-E Address 1501 N Chero County Walton	3-Que Restaurant	Resource Typ Resource Us Date of Cons House Type Barn Type Church Type Commercial School Type Structural Sy Style Roof Exterior Clad Foundation Porch Windows	oe Building e Vacant truction 1970-1979 Ranch Type Restaurant stem Concrete block No academic style Gable: side
Preliminary A Not eli		Status - Listed Not listed		Applicable Criteria C



Preliminary Assessment	Status - Listed	Applicable Criteria
Potentially Eligible	Not listed	С

Style

Roof

Porch

Windows

Chimney

Alterations

No academic style

Double hung sash: 6/6

No chimney observed

Replacement materials


Veneer: brick, running bond

Hip


Foundation Continuous: brick

Recessed

Exterior Cladding



	Social Circle Historic Resource Resource ID SC-74		NARGHIS ID 65144		
OF ENVIRO			Resource Type Building		
Landscape architecture + D historic preservation peg	Address 230 South Cher	rokee Rd		Commercial: Single retail ction 1920-1929	
Performant action of the environment al ethics of the environment al et	County Walton		RoofGaExterior CladdinFoundationPiePorchVeWindowsDo	m Balloon frame aftsman ble: front ng Wood: weatherboard	
Preliminary A Eligit		Status - Listed Listed		Applicable Criteria C	





Resource ID SC-76

Address 431 N. Cherokee Rd

County Walton



NARGHIS ID 240617 **Resource Type** Building **Resource Use** Residential: Single Family Dwelling Date of Construction 1910-1919 Gabled ell cottage **House Type** Barn Type **Church Type Commercial Type School Type** Structural System Balloon frame Folk Victorian: elements Style Roof Gable: cross Exterior Cladding Wood: weatherboard Foundation Continuous: brick Porch Verandah Windows Double hung sash: 6/6 Chimney Gable end exterior; Center: brick Alterations Additions

Preliminary Assessment	Status - Listed	Applicable Criteria	
Eligible	Listed	С	




	Social Circle Historio	c Resource	NARGHIS ID 240662
5 JO AL	Resource ID SC-78		Resource Type Building
Landscape architecture	Address 309 W Highte		Resource UseResidential: Single Family DwellingDate of Construction1905-1914
 historic preservation of the second se	County Walton		House Type Georgian House
			Barn Type
100		the second of the second se	Church Type
19			Commercial Type
15000			School Type
	and the second second second		Structural System Balloon frame
			Style Neoclassical Revival
			Roof Hip
			Exterior Cladding Wood: weatherboard
		ALC UP	Foundation Unknown
			Porch Verandah, Balcony
			Windows Double hung sash
			Chimney Off center within roof surface: brick
Je and	Y		Alterations
Preliminary A	ssessment	Status - Listed	Applicable Criteria
Eligi		Listed	c c

RGIA	Social Circle Historic	c Resource	NARGHIS ID 240665	
	Resource ID SC-79 Address 291 W Highte County Walton		Resource Type Building Resource Use Residential:Single Family Dwelling Date of Construction 1880-1889 House Type Georgian House Barn Type Church Type Church Type Commercial Type School Type Structural System Style Georgian, Greek Revival: elements Roof Hip Exterior Cladding Wood: weatherboard Foundation Unknown Porch Verandah Windows Double hung sash: 1/1 Chimney Off-ctr within roof surf, Lateral exterior Alterations Additions, Replacement materials	
Preliminary A		Status - Listed	Applicable Criteria	
Eligi	ible	Listed	C	
	Social Circle Historic Resource		NARGHIS ID 240668	
OF ENVIRO	Resource ID SC-80		Resource Type Building	
	Address Approximately 225 W Hightower Tr		Resource Use Residential: Single Family Dwellin Date of Construction 1890-1889	
Landscape architecture	Address Approximately 2	25 W Hightower Tr	Date of Construction 1890-1889	



Queen Anne House House Type Barn Type Church Type **Commercial Type** School Type Structural System Balloon frame Style Queen Anne Complex Roof Exterior Cladding Wood: weatherboard Foundation Unknown Porch Wrap-around Double hung sash: 2/2 Windows Chimney Off center within roof surface: brick Alterations

Preliminary Assessment	Status - Listed	Applicable Criteria
Eligible	Listed	С



	Social Circle Histori	c Resource	NARGHIS ID 240685
	Resource ID SC-82 Address 213 W Hight County Walton		Resource TypeBuildingResource UseResidential: Single Family DwellingDate of Construction1890-1889House TypeHall-parlorBarn TypeHall-parlorBarn TypeSchool TypeSchool TypeBalloon frameStructural SystemBalloon frameStyleNo academic styleRoofGable: side, multiExterior CladdingWood: weatherboardFoundationContinuous: concretePorchVerandahWindowsDouble hung sash: 6/6ChimneyOff center within roof surface: brickAlterationsAdditions, replacement materials
Preliminary A Eligi		Status - Listed Listed	Applicable Criteria C





Social Circle Historic Resource Resource ID SC-84


Address 195 W Hightower Tr

County Walton



NARGHIS ID 240687					
Resource Ty	pe Building				
Resource Us	e Residential: Single Family Dwelling				
Date of Cons	truction 1920-1929				
House Type	English cottage				
Barn Type					
Church Type					
Commercial	Туре				
School Type					
Structural Sy	vstem Balloon frame				
Style	English vernacular				
Roof	Gable: multi, complex				
Exterior Clac	Iding Brick: common				
Foundation	Unknown				
Porch	No porch				
Windows	Double hung sash: 6/6, 4/4; Fixed				
Chimney	Gable end exterior: brick				
Alterations	Additions				

Preliminary Assessment	Status - Listed	Applicable Criteria	
Eligible	Listed	С	



	Social Circle Historic	c Resource	NARGHIS ID 240271
D JO L	Resource ID SC-86		Resource Type Building
Lister in the second se	Address 147 South Fo County Walton	orest Ave	Resource UseResidential: Single Family DwellingDate of Construction1945-1954House TypeBungalow: side gableBarn TypeChurch Type
			Commercial Type School Type Structural System Balloon frame Style Craftsman Roof Gable: side
			Exterior CladingWood: weatherboardFoundationContinuous: brickPorchStoop: frontWindowsDouble hung sash: 3/1ChimneyOff ctr within roof surface: brickAlterationsAddition
Preliminary A Not Eli		Status - Listed Not listed	Applicable Criteria C




County Walton



Date of Construction 1970-1979 Ranch **House Type** Barn Type **Church Type Commercial Type School Type** Structural System Brick bearing No academic style Style Roof Gable: side **Exterior Cladding** Brick Foundation Unknown Porch Recessed Windows Double hung sash: 6/6 Chimney Off ctr within roof surface: brick Alterations

Preliminary Assessment	Status - Listed	Applicable Criteria
Not eligible	Not listed	С



Social Cir	cle Historic Resource	NARGHIS ID 240275
Resource ID	SC-90	Resource Type Building
Address 1 historic preservation pro- te environmental ethics of County Wa	79 South Forest Ave	Resource Use Residential: Multi Family Dwelling: duplex Date of Construction 1910-1919 House Type Central Hallway Barn Type Church Type
		Commercial Type School Type Structural System Balloon frame Style Greek revival: elements Roof Gable: side Exterior Cladding Wood, Synthetic siding: masonite Foundation Unknown
		PortionOnknownPorchPortico: frontWindowsDouble hung sash: 6/6ChimneyGable end interiorAlterationsAdditions
Preliminary Assessment Not eligible	Status - Listed Not listed	Applicable Criteria C

Address 167 West Hightower Tr Resource Use Resource Use Date of Construction	ilding esidential: Single Family Dwelling n 1945-1954
Address 167 West Hightower Tr Distoric preservation of Construction	e , e
were planning + design v	
	de Gable Cottage
Barn Type	
Church Type	
Commercial Type	
School Type	
Structural System	Balloon frame
Style No acad	lemic style
Roof Gable: s	side
Exterior Cladding	Brick: common bond
Foundation Continue	ous: concrete
Porch Stoop	
Windows Double	hung sash: 1/1; Fixed
Chimney Off cent	er, ridgeline: brick
Alterations Enclose	d side porch
Preliminary Assessment Status - Listed App	olicable Criteria
Eligible Listed	С



Social Circle Historic Resource

Resource ID SC-92 Wiley General Store

Address 109 Cherokee Rd

County Walton



NARGHIS ID 64933 **Resource Type** Building **Resource Use** Commercial: General Store Date of Construction 1898 House Type Barn Type Church Type **Commercial Type** Commercial block: multiple retail School Type Structural System Masonry Style Folk Victorian Roof Flat

 Exterior Cladding
 Brick

 Foundation
 Continuous: brick


 Porch
 Recessed

 Windows
 Double hung sash: 2/2; Fixed (2)

 Chimney
 No chimney observed

 Alterations
 Fixed set (2)

Preliminary Assessment	Status - Listed	Applicable Criteria	
Eligible	Listed	C	



FENVIRO	Res
C E+D	Add
interic processation	

H env. planning + design SGN environmental ethics

source ID SC-94


dress 113 Cherokee Rd


County Walton



Resource Ty	rpe Building		
Resource Us	se Vacant		
Date of Cons	struction ¹⁸⁹⁰⁻¹⁸⁹⁹		
House Type			
Barn Type			
Church Type	9		
Commercial	Type Commercial block: multiple retail		
School Type			
Structural System Masonry			
Style	Folk Victorian		
Roof	Flat		
Exterior Cla	dding Brick		
Foundation	Continuous: brick		
Porch	No porch		
Windows	Fixed		
Chimney	No chimney observed		
Alterations			


Preliminary Assessment Status - Listed **Applicable Criteria** Eligible Listed С







Social Circle Historic Resource Resource ID SC-98 Address 137 S. Cherokee Rd Date of Construction 1895-1904
UEUM Address 137 S Charokoo Dd
E environmental ethics 2 County Walton House Type
Barn Type Church Type Commercial Type Commercial Block: Multiple reta School Type
Structural System Masonry
Style Folk Victorian
Roof Unknown
Exterior Cladding Brick
Foundation Unknown
Porch No porch
Windows Fixed
Chimney No chimney
Alterations Replacement materials
Preliminary Assessment Status - Listed Applicable Criteria
Eligible Listed C

COLLEG	Social Circle Historic Resource		NARGHIS ID 64927
Andread and a second and a seco	Social Circle Historic Resource Resource ID SC-99 Address 147 S. Cherokee Rd County Walton		NARGHIS ID 64927 Resource Uye Building Resource Use Commercial: Single Retail Date of Construction 1895-1904 House Type Barn Type Church Type Commercial Block: Multiple Retail School Type Structural System Masonry Style Folk Victorian Roof Flat
Preliminary A Eligi		Status - Listed Listed	Exterior Cladding Brick Foundation Unknown Porch Recessed Windows Fixed: single Chimney No chimney Alterations Replacement materials
	<section-header><text><text><text><text></text></text></text></text></section-header>		NARGHIS ID 240371 Resource Type Building Resource Use Commercial: Single Retail Date of Construction 1895-1904 House Type Barn Type Church Type Commercial Type Commercial Block: Multiple retail School Type Structural System Masonry Stype Field Material System Masonry Stype Field Material System Masonry Stype Field Material System Masonry Material System Material System Masonry Material System Materia
Preliminary A Eligi		Status - Listed	Applicable Criteria C








Preliminary Assessment	Status - Listed	Applicable Criteria	
Eligible	Listed	С	




	Social Circle Historic	Resource	NARGHIS ID 240911
D 10 Y	Resource ID SC-106 Address 347 Hickory St		Resource Type Building
historic preservation provide the servation of the servat			Resource Use Residential: Single Family Dwelling Date of Construction 1965-1974
env planning + design S	County Walton		House TypeRanchBarn TypeChurch TypeCommercial TypeSchool TypeSchool TypeStructural SystemPost-and-beamStyleNo academic styleRoofGable: sideExterior CladingVeneer: brickFoundationContinuous: concretePorchPorticoWindowsDouble hung sash: 1/1ChimneyAlterationsLarge rear addition
Preliminary A Not Eli		Status - Listed Not Listed	Applicable Criteria C

	Social Circle Historio	c Resource	NARGHIS	ID 240432
OF ENVIR	Resource ID SC-107		Resource Ty	/pe Building
Landscape architecture	Address 359 B Hickor	359 B Hickory Dr		se Residential: Single Family Dwelling struction 1950-1959
Historic preservation of Henv. planning + design Sign Henvironmental ethics	County Walton		House Type	Devial
			Barn Type	
SLO	and the second s		Church Type	9
-OW	and the second		Commercial	Туре
CHILL			School Type	
AT PLAY	1. A. 7		Structural S	-
			Style	No academic style
			Roof	Нір
			Exterior Cla	dding Wood: weatherboard; Veneer: brick
			Foundation	Concrete: continuous
			Porch	Portico
	a service and the service of the ser		Windows	Double hung: 1/1, 6/6
			Chimney	No chimney observed
			Alterations	Addition
Preliminary A	ssessment	Status - Listed		Applicable Criteria
Not Eli	gible	Not listed		С




NARGHIS	^d 64939		
Resource Ty	pe Building		
Resource Us	e Residential: Single Family Dwelling		
Date of Cons	truction 1905-1914		
House Type	Saddlebag: 2 door		
Barn Type			
Church Type			
Commercial	Туре		
School Type			
Structural Sy	stem Balloon frame		
Style	No academic style		
Roof	Gable: side		
Exterior Clac	Iding Wood: weatherboard		
Foundation	Pier with infill: brick		
Porch	Verandah		
Windows	Double hung sash: 9/9		
Chimney	Center ridgeline: brick		
Alterations	Replacement materials		

Preliminary Assessment	Status - Listed	Applicable Criteria
Eligible	Listed	С



GE OR GLA	Social Circle Historic	Resource	NARGHIS ID 240434
D JO AJ	Resource ID SC-110		Resource Type Building
C E + D Iandscape architecture	Address 302 Hickory S	St	Resource UseResidential: Single Family DwellingDate of Construction1965-1974
Historic preservation of Henv. planning + design Sign Henvironmental ethics	County Walton		House Type Ranch
			Barn Type
and the second sec	< TABLES AND		Church Type
No.			Commercial Type
	San Brand MA		School Type
			Structural System Post and Beam
			Style No academic style
NO P			Roof Gable: side
	AT LAND		Exterior Cladding Synthetic siding: vinyl
		Contrast Of Survey of Street	Foundation Unknown
	C CORRECTION AND	and the second second	Porch Portico
Con Tanada	and the second second second second		Windows Double hung sash: 6/6
· Serima ·			Chimney Gable end: vinyl siding
			Alterations
Preliminary A	ssessment	Status - Listed	Applicable Criteria
Not eli		Not listed	C
	[





Resource ID SC-112

Address 500 Hickory St

County Walton




NARGHIS	^{ID} 240436		
Resource Ty	pe Building		
Resource Us	e Residential: Single Family Dwelling		
Date of Cons	struction ¹⁹³⁵⁻¹⁹⁴⁴		
House Type	Bungalow: side gable		
Barn Type			
Church Type			
Commercial	Туре		
School Type			
Structural Sy	stem Balloon frame		
Style	No academic style		
Roof	Gable: side		
Exterior Clac	Iding Synthetic siding: asbestos		
Foundation	Pier with infill: brick		
Porch	Verandah		
Windows	Double hung: 1/1, 9/9		
Chimney	Both gable ends, exterior,brick		
Alterations	Replacement materials, addition		

Preliminary Assessment	Status - Listed	Applicable Criteria	
Not eligible	Not listed	С	



	Social Circle Historic Resource		NARGHIS ID 240437	
OF ENVIR	Resource ID SC-114		Resource Type Building	
C E + D landscape architecture	Address 350 Hickory	Dr	Resource UseResidential: Single Family DwellingDate of Construction1950-1959	
Historic preservation DES Henv. planning + design SSR Henvironmental ethics S	County Walton		House Type Bungalow: hip	
			Barn Type	
			Church Type	
			Commercial Type	
			School Type	
		a for the second	Structural System Post and beam	
			Style No academic style	
			Roof Hip	
			Exterior Cladding Brick	
			Foundation Continuous: brick	
and the second	And the second second		Porch Verandah	
	And the second second	and the second second	Windows Double hung: 2/2	
a state of the	A CONTRACTOR OF A CONTRACTOR O		Chimney No chimney observed	
		A DALLAR	Alterations	
Preliminary A	ssessment	Status - Listed	Applicable Criteria	
Not Elig		Not listed	C	



Preliminary Assessment Eligible

Status - Listed Listed

Applicable Criteria С



Social Circle Historic Resource Resource ID SC-116


Address 177 E Hightower Tr

County Walton





NARGHIS	^{ID} 240460
Resource Ty	r pe Building
Resource Us	Residential: Single Family Dwelling
Date of Cons	struction 1872, 1940, 1998
House Type	Georgian cottage
Barn Type	
Church Type)
Commercial	Туре
School Type	
Structural S	ystem Balloon frame
Style	Folk victorian
Roof	Gable: front, side
Exterior Cla	dding Wood: weatherboard
Foundation	Brick
Porch	Verandah
Windows	Double hung sash: 6/6; Fixed
Chimney	Gable end interior: brick
Alterations	Additions; Replacement materials

Preliminary Assessment	Status - Listed	Applicable Criteria	
Eligible	Listed	С	




	Social Circle Historic	c Resource	NARGHIS ID 240464
D 40 Y	Resource ID SC-118		Resource Type Building
Le devironmental ethics environmental ethics	Address 152 S. Dogw County Walton	vood Ave	Resource UseResidential: Single Family DwellingDate of Construction1885-1894House TypeNew South CottageBarn TypeChurch TypeChurch TypeCommercial TypeSchool TypeStructural SystemStructural SystemBalloon frameStyleSecond EmpireRoofMansardExterior CladdingWood: weatherboardFoundationUnknownPorchVerandahWindowsDouble hung sash: 2/2ChimneyOff ctr within roof surf: brickAlterationsSecond Second Secon
Preliminary A Eligi		Status - Listed Listed	Applicable Criteria C






NARGHIS	^D 240466
Resource Ty	pe Building
Resource Us	e Residential: Single Family Dwelling
Date of Cons	truction 1900-1909
House Type	Gabled ell house
Barn Type	
Church Type	
Commercial	Туре
School Type	
Structural Sy	stem Balloon frame
Style	Folk victorian
Roof	Gable: multi
Exterior Clac	Iding Wood: weatherboard
Foundation	Continuous: brick
Porch	Wrap-around
Windows	Double hung sash: 2/2
Chimney	Center, Off-ctr ridgeline: brick
Alterations	

Preliminary Assessment	Status - Listed	Applicable Criteria	
Eligible	Listed	С	



	Social Circle Historio	c Resource	NARGHIS ID	240467
OF ENVIR	Resource ID SC-122		Resource Type	Building
Diandscape architecture + Diantico preservation of the sign of the	Address 241 E Highto County Walton	ower Tr	Resource Use Date of Constru House Type	Residential: Single Family Dwelling uction 1900-1909 Queen Anne Cottage
4 environmental ethics 9			Barn Type Church Type Commercial Ty School Type Structural Syst Style Fo	pe em Balloon frame olk victorian, Queen Anne omplex
			FoundationccPorchWWindowsDChimneyO	-
Preliminary A		Status - Listed Listed		Applicable Criteria C





Social Circle Historic Resource

Resource ID SC-124

Address 623 Wildwood Dr

County Walton



NARGHIS ID 240380 **Resource Type** Building **Resource Use** Residential: Single Family Dwelling Date of Construction 1934-1944 Bungalow: front gable **House Type** Barn Type **Church Type Commercial Type School Type** Structural System Balloon frame Style No academic style Roof Gable: front

Exterior CladdingSynthetic siding: vinylFoundationContinuous: concretePorchVerandahWindowsDouble hung sash: 6/6ChimneyOff-ctr ridgeline: brick

Replacement materials

 Preliminary Assessment Not eligible
 Status - Listed Not listed
 Applicable Criteria C

Alterations



	Social Circle Historic F	Resource	NARGHIS ID 240944
OF ENVIR	Resource ID SC-126	F	Resource Type Building
Landscape architecture	Address 641 Wildwood		Resource Use Residential: Single Family Dwelling Date of Construction 1965-1974
D historic preservation D H env. planning + design Sic H environmental ethics Si	County Walton		louse Type Ranch
		B	3arn Type
	A CARACTER AND		Church Type
Contraction of	CARS CONTRACTOR	C	Commercial Type
10		S	School Type
		S	Structural System Post-and-beam
		S	Style No academic style
		Received and a second s	Roof Hip
		E	Exterior Cladding Veneer: brick
		F	Foundation Continuous: concrete
		P	Porch Recessed
and the second second second	and the second	Verse ver	Vindows Double hung sash: 6/6
and the second second	The second s		Chimney Off center within roof surface: brick
MARLEY N			Alterations
Drolimicon	Accoment	Status - Listed	Applicable Criteria
Preliminary A		Not Listed	Applicable Criteria
Not E			






Social Circle Historic Resource Resource ID SC-128

Address 806 Wildwood Dr

County Walton



NARGHIS ID 240393



 Preliminary Assessment
 Status - Listed
 Applicable Criteria

 Not eligible
 Not listed
 C



	Social Circle Histori	c Resource	NARGHIS	^{ID} 240397
Y OF G	Resource ID SC-130		Resource Ty	pe Building
	Address 806 Wildwood Dr, locat	red on same lot with SC-129	Resource Us	
A landscape architecture			Date of Cons	struction 1950-1959
H env. planning + design SC E environmental ethics	County Walton		House Type	Ranch
			Barn Type	
	A CALL THE AND		Church Type	9
			Commercial	Туре
and the second			School Type	
		Mar March	Structural Sy	ystem Balloon frame
	the state of the s		Style	No academic style
			Roof	Нір
			Exterior Cla	dding Synthetic siding: vinyl
			Foundation	Unknown
and the second sec	and the second second second		Porch	Portico
			Windows	Double hung sash: 6/6
			Chimney	No chimney observed
			Alterations	Replacement materials
Preliminary As	ssessment	Status - Listed		Applicable Criteria
Not elig	jible	Not listed		С

	Social Circle Historic	Resource	NARGHIS ID 240398
C E + D Induce per terter ter of the terter	Resource ID SC-131 Address 1280 Wildwoo County Walton	od Dr	Resource TypeBuildingResource UseResidential: Single Family DwellingDate of Construction1965-1974House TypeRanchBarn TypeChurch TypeChurch TypeCommercial TypeSchool TypeStructural SystemPost and beamStyleNo academic styleRoofGable: sideExterior CladdingVeneer: brickFoundationContinuous: concretePorchPorticoWindowsDouble hung: 6/6ChimneyNo chimney observedAlterations
Preliminary A Not eli		Status - Listed Not listed	Applicable Criteria C
OF GEORGIA	Social Circle Historic	Resource	NARGHIS ID 240401
9 40 AL	Resource ID SC-132		Resource Type Building

Address 241 Marco Dr

County Walton

C E⁺D




Building Resource Type Resource Use Residential: Single Family Dwelling Date of Construction 1960-1969 House Type Ranch Barn Type Church Type **Commercial Type** School Type Structural System Post and beam Style No academic style Roof Gable: side, front Exterior Cladding Veneer: brick, common Foundation Continuous: concrete Porch Portico Windows Double hung: 6/6 Chimney No chimney observed Alterations


Preliminary Assessment	Status - Listed	Applicable Criteria	
Not Eligible	Not listed	С	




	Social Circle Histori	c Resource	NARGHIS ID 240403
OF ENVIR	Resource ID SC-134		Resource Type Building
C E+D landscape architecture	Address 251 Marco D)r	Resource Use Residential: Single Family Dwelling Date of Construction 1965-1974
 D historic preservation Design 2010 2 env. planning + design 300 2 environmental ethics 4 	County Walton		House Type Ranch
		_	Barn Type
E.			Church Type
			Commercial Type
			School Type
		- Aller - Aller	Structural System Post and beam
			Style No academic style
		and succession of the	Roof Gable: side, stepped
AN I			Exterior Cladding Brick: common
States_			Foundation Concrete: continuous
the second			Porch Verandah
	and the second	and the second	Windows Double hung sash: 6/6
A State			Chimney No chimney observed
			Alterations
Preliminary A	ssessment	Status - Listed	Applicable Criteria
Not eli		Not listed	C
	<u></u>		









Social Circle Historic Resource Resource ID SC-138 Address 208 Marco Dr Address 208 Marco Dr Address 208 Marco Dr
Env: planning + design B County Walton House Type Ranch
Barn Type
Church Type
Commercial Type
School Type
Structural System Post and Beam
Style No academic style
Roof Gable: side
Exterior Cladding Brick: common
Foundation Brick: continuous
Porch Stoop
Windows Double hung sash: 1/1
Chimney No chimney observed
Alterations
Preliminary Assessment Status - Listed Applicable Criteria
Not Eligible Not Listed C



	Ba	arn Type		
	Cr	hurch Type		
	Co	ommercial Type		
	Sc.	School Type		
	State Sta	ructural System	Post and Beam	
	Style Style	yle No acad	demic style	
	Ro	oof Hip		
	Ex	cterior Cladding	Brick: common	
	Fo	oundation Unknow	'n	
	Po	orch Stoop		
	Wi	indows Double	hung sash: 6/6	
	Cł	himney No chim	nney observed	
Sugar Contraction of the second	Al	terations		
Preliminary Assessment	Status - Listed	Арр	licable Criteria	
Not Eligible	Not Listed		с	



	Social Circle Historic	Resource	NARGHIS ID 2	40412
D 10 L	Resource ID SC-142		Resource Type	Building
CE+D Indscape architecture	Address 417 Collette L	.n	Resource Use R Date of Construction	tesidential: Single Family Dwelling 0n 1965-1974
H env. planning + design S H environmental ethics N	County Walton		House Type F	Ranch
			Barn Type	
and the second se		and the second second	Church Type	
5 5 4 8 5 C			Commercial Type	
1.000		100 L	School Type	
1. 1.			Structural System	Post and Beam
			Style No ac	ademic style
		Red X	Roof Hip	
and the second			Exterior Cladding	Brick: running
		And the second second second	Foundation Brick	
		The second second	Porch Stoop	
		and and	Windows Doubl	e hung sash: 1/1
	e a ser a		Chimney No ch	imney observed
			Alterations	
Preliminary A	ssessment	Status - Listed	Δι	oplicable Criteria
Not eli		Not Listed		C





Resource ID SC-144


Address 235 S. Cherokee Rd

County Walton



Resource Type Building **Resource Use** Residential: Single Family Dwelling Date of Construction 1905-1914 Georgian House **House Type** Barn Type **Church Type Commercial Type School Type** Structural System **Balloon Frame** Style No academic style Roof Hip Brick: running **Exterior Cladding** Foundation Concrete: continuous Porch Verandah Windows Double hung sash: 6/6 Chimney No chimney observed Alterations

Preliminary Assessment	Status - Listed	Applicable Criteria	
Eligible	Listed	С	




CE OR GLA	Social Circle Historic Resource	
40 JO	Resource ID SC-146	Res
LISU CE+D I landscape architecture T	Address 184 South Cherokee Rd	Res Date
N historic preservation + D H env. planning + design C H environmental ethics	County Walton	Hou
		Barr
	1. Sector Sector	Chu Corr
-		Sch
-	the second se	Stru
and the		Styl
M Decis ACE Home Center		Roo Exte
the second		Fou
		Pore
		Win Chir
		Alte

NARGHIS ID 240415

Resource Ty	pe B	uilding		
Resource Us	se Commercial: Hotel			
Date of Construction 1965-1974				
House Type				
Barn Type				
Church Type				
Commercial Type Single retail				
School Type				
Structural System Post-and-bean				
Style	No academic style			
Roof	Mansard			
Exterior Cladding		Brick		
Foundation	Continuous: brick			
Porch	Verandah			
Windows	Fixed			
Chimney	No chimney observed			
Alterations				

Preliminary Assessment Not Eligible Status - Listed Not Listed Applicable Criteria A, C






Church Type Commercial Type Single retail **School Type** Structural System Unknown N/A Style Roof Flat **Exterior Cladding** Brick: running Foundation Brick; Concrete Porch No porch Windows Fixed: single Chimney Off-center within roof surface Replacement materials Alterations

 Preliminary Assessment Not Eligible
 Status - Listed
 Applicable Criteria

 Not Listed
 C



	Social Circle Historio	c Resource	NARGHIS II	P 240426
D JO AJ	Resource ID SC-150		Resource Typ	e Building
Landscape architecture revision of the environmental ethics of the environmental ethic	Address 261 SW Men County Walton	norial St	Resource Use Date of Const House Type Barn Type	e Residential: Single Family Dwelling ruction 1955-1964 Ranch
			Church Type Commercial T School Type Structural Sys Style	
			Exterior Clado Foundation C Porch S Windows D Chimney N	Gable: side ding Brick, Synthetic: vinyl siding Continuous: brick Stoop Double hung sash: 6/6 No chimney observed Replacement materials
Preliminary A Not Eli		Status - Listed Not listed		Applicable Criteria C



Preliminary Assessment Not Eligible

```
Applicable Criteria
C
```

Double hung sash: 2/2

No chimney observed

Synthetic Siding: Vinyl

Exterior Cladding

Porch

Windows


Chimney

Alterations


Foundation Brick: continuous

Recessed

Addition



	Social Circle Historic	Resource	NARGHIS ID 2	240430
7 OF 6	Resource ID SC-154		Resource Type	Building
	Address 428 Branham County Walton	n Cir	Resource Use Date of Construct House Type Barn Type Church Type Commercial Type School Type Structural System Style Colo Roof Hip Exterior Cla∪ding Foundation Unkn Porch Stool Windows Double	Residential: Single Family Dwelling tion 1975-1984 Georgian House n Balloon frame nial revival Brick: common
		_	Alterations	
Preliminary A Not Eli		Status - Listed Not Listed	4	Applicable Criteria C



Preliminary Assessment Not Eligible Brick: running

Double hung sash: 6/6; Fixed (1)

Off-ctr within roof surface: brick

Exterior Cladding

Porch


Windows

Chimney


Alterations

Foundation Brick; Concrete

Arcade



Social Circle Histor	ic Resource	NARGHIS ID 240441
Resource ID SC-158	F	Resource Type Building
Address 265 E Hight	ower Tr	Resource Use Residential: Single Family Dwelling Date of Construction 1975-1984 House Type Ranch Barn Type
	S S S S S S S S S S S S S S S S S S S	Church Type Commercial Type School Type Structural System Post and Beam Style No academic style Roof Gable: side Exterior Cladding Brick: common Foundation Concrete: continuous Porch Recessed Windows Jalousie, Double hung sash: 2/2 Chimney Center ridgeline: brick
		Alterations
Preliminary Assessment Not eligible	Status - Listed Not Listed	Applicable Criteria C





Address 246 E Hightower Tr


County Walton



NARGHIS ID 65153

Building **Resource Type Resource Use** Vacant Date of Construction 1905-1914 Georgian House **House Type** Barn Type **Church Type Commercial Type School Type** Structural System Balloon frame Style Neoclassical revival Roof Gable: side Exterior Cladding Wood: weatherboard Foundation Brick: continuous Porch Verandah; Balcony Windows Double hung sash: 2/2; Fixed Chimney Gable-end exterior; Off-ctr within roof: brick Alterations

Preliminary Assessment	Status - Listed	Applicable Criteria	
Eligible	Listed	С	



	Social Circle Historic	c Resource	NARGHIS I	□ 240982	
Y OF G	Resource ID SC-162		Resource Typ	be Building	
CE+D Indiscape architecture PEGGO Henv: planning + design HE env:romental ethics	Address Birch Circle at Hill Ave County Walton		Resource Use Residential: Single Family I Date of Construction 1920-1929 House Type Bungalow: cross gabl Barn Type		
			Church Type Commercial School Type	Гуре	
			Structural Sy	stem Balloon frame	
				Colonial revival	
			Roof	Complex hip	
			Exterior Clad	ding Brick: common bond	
			Foundation	Brick; Concrete: continuous	
3696.5	Line Barris	And the second s	Porch	Verandah: 2nd floor; Wrap-around	
			Windows	Double hung sash: 1/1	
The second second			Chimney	Off-center ridgeline; Center: brick	
Carl And			Alterations		
Preliminary A Eligi		Status - Listed Listed		Applicable Criteria C	






NARGHIS ID 240245

Resource Ty	pe Buil	ding		
Resource Use Vacant				
Date of Cons	struction	1955-1964		
House Type				
Barn Type				
Church Type				
Commercial	Туре	Single retail:gas station		
School Type				
Structural Sy	/stem	Balloon frame		
Style	No acad	emic style		
Roof	Hip; Con	nplex		
Exterior Clac	lding	Concrete block		
Foundation	Concrete	e: slab		
Porch	No porch	ı		
Windows	Fixed			
Chimney	No chim	ney observed		
Alterations				

 Preliminary Assessment
 Status - Listed
 Applicable Criteria

 Not eligible
 Not Listed
 C



NARGHIS ID 240246

Building **Resource Type** Vacant **Resource Use** Date of Construction 1910-1919 Georgian house House Type Barn Type **Church Type Commercial Type** School Type Balloon frame Structural System Neoclassical revival Hip **Exterior Cladding** Wood: weatherboard Foundation Continuous: concrete Porte cochere; Arcade; Stoop; Balcony Double hung sash: 1/1 Windows Off-center within roof surf: brick Chimney Alterations

Preliminary Assessment Eligible

Status - Listed Listed


Applicable Criteria С


	Social Circle Historic Resource	NARGHIS	^{ID} 24(
OF ENVIR	Resource ID SC-166	Resource Ty	pe Build
C E + D	Address 163 N Cherokee Rd	Resource Us Date of Cons	
D historic preservation P H env. planning + design SG H environmental ethics	County Walton	House Type	Geo
		Barn Type	
		Church Type	;
San Sha	the man and the second se	Commercial	Туре
		School Type)
		Structural S	ystem I
		Style	Colonial I
		Roof	Hip
	SALON CU	Exterior Cla	dding
	170.464.3616	Foundation	Continuo
		Porch	Verandał
	19 10 10 10 10 10 10 10 10 10 10 10 10 10	Windows	Double h
14		Chimney	Off-cente
		Alterations	

0248

Resource Ty	pe Building				
Resource Us	e Commercial: single retail				
Date of Cons	truction 1905-1914				
House Type	Georgian cottage				
Barn Type					
Church Type					
Commercial	Туре				
School Type					
Structural Sy	stem Balloon frame				
Style	Colonial revival				
Roof	Hip				
Exterior Clac	Iding Wood: weatherboard				
Foundation	Continuous: concrete				
Porch	Verandah				
Windows	Double hung: 1/1, 2/2				
Chimney	Off-centerr within roof surf: brick				
Alterations					

Preliminary Assessment	Status - Listed	Applicable Criteria	
Eligible	Listed	С	







NARGHIS ID	65 ⁻	131
Resource Type	Buil	ding
Resource Use	Vac	ant
Date of Construc	ction	1905-1914


Georgian cottage House Type Barn Type **Church Type Commercial Type School Type** Structural System Balloon frame Style Colonial revival Roof Gable: side; Hip **Exterior Cladding** Wood: weatherboard Foundation Unknown Porch Verandah Windows Double hung sash: 6/6 Chimney Off-center within roof surf: stucco Alterations

Preliminary Assessment Eligible	Status - Listed Listed	Applicable Criteria C	
	Lioted	Ű	i i




	Social Circle Historio	c Resource	NARGHIS	^{ID} 65133	
5 JO A	Resource ID SC-170	esource ID SC-170		pe Building	
Landscape architecture	Address 271 N Cherokee Rd		Resource Use Residential: Single family dwelling Date of Construction 1905-1914		
 historic preservation H env. planning + design E environmental ethics 	County Walton		House Type	New South cottage	
			Barn Type		
		and and the second	Church Type	•	
			Commercial		
	A MAN		School Type		
A CONTRACTOR			Structural Sy		
			Style	Folk Victorian	
			Roof	Gable: multi	
	小学学		Exterior Clac	dding Wood: weatherboard	
	Star A Planta	and the second second	Foundation	Continuous: brick	
		- Contraction	Porch	Verandah	
			Windows	Double hung: 6/6	
a second and			Chimney	Off-center ridgeline: brick	
			Alterations		
Preliminary A	ssessment	Status - Listed		Applicable Criteria	
Eligi		Listed		C	





NARGHIS	^{ID} 240262
Resource Ty	pe Building
Resource Us	Residential: Single family residential
Date of Cons	struction ¹⁹¹⁵⁻¹⁹²⁴
House Type	Georgian cottage
Barn Type	
Church Type	•
Commercial	Туре
School Type	
Structural Sy	ystem Balloon frame
Style	Colonial revival
Roof	Gable: side
Exterior Clad	dding Wood: weatherboard
Foundation	Brick: continuous
Porch	Verandah
Windows	Double hung sash: 6/6; 4/4
Chimney	Center; Off-center ridgeline: brick
Alterations	

Preliminary Assessmen	t	Status - Listed	Applicable Criteria	
Potentially eligible		Not Listed	С	



	Social Circle Historio	c Resource	NARGHIS	^D 65135
D 10 VIR	Resource ID SC-174		Resource Ty	pe Building
And Scape architecture P historic preservation env. planning + design env. planning + design	Address 375 N Chero County Walton	kee Road	Resource Us Date of Cons House Type	e Vacant t ruction 1910-1919 Georgian House
			Roof Exterior Clad Foundation Porch	Type vstem Balloon frame Neoclassical revival Hip Iding Wood: weatherboard Brick: continuous Wrap-around; Portico
			Windows Chimney Alterations	Double hung: 1/1 Center; Off-ctr ridgeline; Gable end: brick
Preliminary A Eligi		Status - Listed Listed		Applicable Criteria C




Address 435 N Cherokee Rd

County Walton




NARGHIS	^{ID} 65136
Resource Ty	pe Building
Resource Us	e Residential: Single family residential
Date of Cons	struction 1910-1919
House Type	New South cottage
Barn Type	
Church Type	
Commercial	Туре
School Type	
Structural Sy	vstem Balloon frame
Style	Craftsman
Roof	Gable: multi
Exterior Clac	Iding Wood: weatherboard
Foundation	Brick: continuous
Porch	Verandah
Windows	Double hung: 1/1, 2/2; Fixed
Chimney	Center; Off-center ridgeline; Gable end: brick
Alterations	Replacement materials

Droliminory Accessmen	Status Listad	Applicable Criteria	
Preliminary Assessmen	Status - Listed	Applicable Criteria	
Eligible	Listed	С	



	Social Circle Histori	c Resource	NARGHIS	^{ID} 240268
0 J OF G	Resource ID SC-178		Resource Ty	pe Building
Bandscape architecture historic preservation H env: planning + design env: planning + design	Address 511 N Cherc County Walton	okee Rd	Resource Us Date of Cons House Type	struction ¹⁸⁸⁷
			Barn Type Church Type Commercial School Type Structural Sy Style	Туре
			Roof Exterior Clac Foundation Porch Windows Chimney Alterations	Gable: style dding Synthetic siding: vinyl Continuous: brick Stoop; Porte-cochere Double hung sash: 6/1 Gable end exterior: brick Multiple additions; Replacement materials
Preliminary Not el		Status - Listed Not Listed		Applicable Criteria C





440.0


Address 149 Sycamore St

County Walton



NARGHIS ID 240379 **Resource Type** Building **Resource Use** Commercial: single retail Date of Construction 1910-1919 Shotgun **House Type** Barn Type **Church Type Commercial Type Business School Type** Balloon frame Structural System No academic style Style Roof Gable: front **Exterior Cladding** Wood: weatherboard Foundation Unknown Porch Verandah Windows Double hung sash: 2/2; Fixed Chimney Center: brick Alterations Multiple additions; Replacement materials

Preliminary Assessment	Status - Listed	Applicable Criteria	
Eligible	Listed	С	



	Social Circle Historic	c Resource	NARGHIS ID	
OF ENVIR	Resource ID SC-182		Resource Type	Building
C E+D landscape architecture	Address 166 Sycamo	re St	Resource Use Date of Construc	Residential: Single Family Dwelling tion 1900-1909
H env. planning + design Sign H environmental ethics	County Walton		House Type	New South Cottage
			Barn Type	
			Church Type	
			Commercial Type	e
		p	School Type	
			Structural System	m Balloon frame
			Style Foll	k Victorian
		A CONTRACTOR	Roof Gat	ble: front; hip
		T	Exterior Cladding	g Wood: drop siding; weatherboard
			Foundation Cor	ntinuous: brick
AND CONTRACTOR OF THE OWNER	AND		Porch Ver	andah
	- martes esciptures		Windows Dou	uble hung sash: 2/2
		Table 1 Martin Carlos	Chimney Off-c	center within roof surface: brick
			Alterations	
			_	
Preliminary A	ssessment	Status - Listed		Applicable Criteria
Eligi	ble	Listed		С



County Walton


nv. planning + design nvironmental ethics

Ξ





Date of Construction 1935-1944 **House Type** Barn Type **Church Type Commercial Type** Single retail **School Type** Concrete frame Structural System Style No academic style Roof Flat **Exterior Cladding** Concrete block Foundation Concrete Porch None Windows Unknown Chimney None Alterations

Preliminary Assessment	Status - Listed	Applicable Criteria	
Not eligible	Listed	С	



	Social Circle Historio	c Resource	NARGHIS ID	240391
OF ENVIR	Resource ID SC-186		Resource Type	Building
And State of the s	Address 151 S. Dogw	rood Ave		Residential: Single Family Dwelling uction 1905-1914
E environmental ethics 2	County Walton		House Type Barn Type Church Type Commercial Ty School Type Structural Syst	-
			Roof H Exterior Claddi Foundation C Porch V Windows D Chimney O	olonial Revival ip ing Wood, weatherboard ontinuous: brick erandah ouble hung sash: 1/1 and 2/2 iff center within roof surface: brick nclosed verandah
	Assessment ible	Status - Listed Listed		Applicable Criteria C






NARGHIS ID 240394 **Resource Type** Building **Resource Use** Residential: Single Family Dwelling Date of Construction 1910-1919 Gabled ell cottage **House Type** Barn Type **Church Type Commercial Type School Type** Structural System Balloon frame No academic style Style Roof Cross gable **Exterior Cladding** Wood: weatherboard Foundation Brick Porch Verandah Windows Double hung sash: 1/1, 2/2 Chimney Alterations

Preliminary Assessment	Status - Listed	Applicable Criteria	
Eligible	Listed	С	



	Social Circle Histori	c Resource	NARGHIS	^{ID} 240399
OF ENVI	Resource ID SC-190		Resource Ty	pe Building
	Address 155 Holly Av		Resource Us	o , o
historic preservation		<u> </u>	Date of Cons	struction 1910-1919
H env. planning + design Sign F environmental ethics	County Walton		House Type	Queen Anne cottage
24 Car			Barn Type	
			Church Type	
			Commercial	Туре
			School Type	
and the second sec			Structural Sy	stem Balloon frame
			Style	Queen Anne
			Roof	Hip, front gable
			Exterior Clac	Iding Wood: weatherboard
			Foundation	Continuous: brick
			Porch	Verandah
and the second second	and the second		Windows	Double hung sash: 9/9
and the second second	Turner and the		Chimney	Off center within roof surface: brick
			Alterations	Rear addition
Preliminary	Assessment	Status - Listed		Applicable Criteria
Potentia	lly Eligible	Not listed		С





Address 128 Hollis Ave


County Walton




Resource Ty	/pe Building			
Resource Us	se Residential: Single Family Dwelling			
Date of Cons	struction ¹⁹⁴⁵⁻¹⁹⁵⁴			
House Type	Side gable cottage			
Barn Type				
Church Type	9			
Commercial	Туре			
School Type	•			
Structural System Balloon frame				
Style	Colonial revival			
Roof	Gable: side			
Exterior Cla	dding Synthetic siding: Asbestos			
Foundation	Brick: continuous			
Porch	Verandah; Stoop			
Windows	Double hung sash: 8/8			
Chimney	Off-center ridgeline: brick			
Alterations	Screened in porch			

 Preliminary Assessment
 Status - Listed
 Applicable Criteria

 Potentially eligible
 Not listed
 C



GEORGIA	Social Circle Historic	Resource	NARGHIS I	□ 240418
Y OF G	Resource ID SC-194		Resource Typ	be Building
Landscape architecture	Address 156 S. Holly S	Idress 156 S. Holly St		e Residential: Single Family Dwelling truction 1920-1929
 historic preservation env. planning + design environmental ethics 			House Type	Bungalow: side gable
			Barn Type	
	and the states		Church Type	
	A AND AND AND AND AND AND AND AND AND AN		Commercial	Туре
and the second sec		A SET A	School Type	
			Structural Sy	stem Balloon frame
			Style	Craftsmen; English Vernacular
	T-INI A IMML		Roof	Gable: side
			Exterior Clad	ding Synthetic siding: Vinyl
÷.			Foundation	Continuous: concrete
			Porch	Verandah; Stoop
	The second second second		Windows	Double hung sash: 3/1
		Sector Car	Chimney	Lateral exterior: brick
Sec. 1		State State	Alterations	Replacement materials, enclosed porch
_			_	
Prelimina	ry Assessment	Status - Listed		Applicable Criteria
	t eligible	Not listed		c
-			L	





Resource ID SC-196


Address 182 Holly Ave

County Walton



NARGHIS ID 240420 **Resource Type** Building **Resource Use** Residential: Single Family Dwelling Date of Construction 1910-1919 Georgian cottage **House Type** Barn Type **Church Type Commercial Type School Type** Balloon frame Structural System Colonial revival elements Style Roof Hip **Exterior Cladding** Wood: weatherboard Foundation Unknown Porch Portico Windows Double hung sash: 2/2 Chimney No chimney observed Alterations Enclosed porch

Preliminary Assessment	Status - Listed	Applicable Criteria	
Potentially eligible	Not listed	С	



	Social Circle Historio	c Resource	NARGHIS ID 240422
9 JO AL	Resource ID SC-198	R	Resource Type Building
Le che de la constant	Address 174 Dogwoo County Walton	d Ave	Resource Use Residential: Single Family Dwelling Date of Construction 1910-1919 House Type Bungalow: cross gable Barn Type Church Type Church Type Commercial Type School Type Balloon frame Structural System Balloon frame Style No academic style Roof Gable: cross Exterior Cladding Wood: weatherboard Foundation Pier with infill: brick Porch Verandah Windows Double hung sash: 1/1 Chimney Off-center ridgeline: brick with stucco Alterations Screened porch
Preliminary A Eligil		Status - Listed Listed	Applicable Criteria C





Resource ID SC-200 Gibbs Barton Woodstock


Address 478 N Hightower Rd

County Walton



NARGHIS ID 240502 **Resource Type** Building **Resource Use** Residential: Single Family Dwelling Date of Construction 1910-1919 Queen Anne House **House Type** Barn Type **Church Type Commercial Type School Type** Balloon frame Structural System Style Colonial revival Roof Complex hip **Exterior Cladding** Wood: weatherboard; Concrete Foundation Brick; Concrete: continuous Porch Verandah; Wrap-around Windows Double hung sash: 1/1 Chimney Off-center ridgeline; Center: brick Alterations

Preliminary Assessment	Status - Listed	Applicable Criteria	
Potentially eligible	Not listed	С	





COLLEGE OF EN	Social Circle Historic Resource		NARGHIS ID 240504
ap 10 TY OF GE	Resource ID SC-203		Resource Type Building
Landscape architecture +	Address 586 Hightower Tr		Resource Use Residential: Single family dwelling Date of Construction ¹⁹⁶⁰⁻¹⁹⁶⁹
 D historic preservation B env. planning + design E environmental ethics 	County Walton		House Type Ranch
Simo			Barn Type
	MARCE NO		Church Type
	MAN AND AND AND		Commercial Type
	A MARCELLE		School Type
	1 Martin Law		Structural System Post and beam
			Style No academic style
			Roof Gable: cross
and the second			Exterior Cladding Brick: running bond
11			Foundation Continuous: Brick
	Assessment of		Porch Portico
- Andrews			Windows Double hung sash: 4/4
1 Breat			Chimney No chimney observed
			Alterations
Preliminary A	Assessment	Status - Listed	Applicable Criteria
Not Eli		Not listed	с

<u>۳</u>
ЧO
C E + D Indecape architecture
Z landscape architecture
 historic preservation env. planning + design
u env. planning + design environmental ethics

Resource ID SC-204


Address 680 W. Hightower Tr

County Walton




NARGHIS ID 240505 Building **Resource Type Resource Use** Residential: Single family dwelling Date of Construction 1960-1969 Ranch House Type Barn Type Church Type **Commercial Type** School Type Structural System Balloon frame Style No academic type Roof Hip Exterior Cladding Wood: weatherboard Foundation Continuous: Brick Porch Verandah Windows Double hung sash: 9/9 Chimney Off center within roof surface: brick Alterations

Preliminary Assessment	Status - Listed	Applicable Criteria	
Not Eligible	Not listed	С	



	Social Circle Histor	ric Resource	IARGHIS II	P 240519
OF ENVIR	Resource ID SC-206	F	Resource Typ	e Building
Andscape architecture historic preservation env. planning + design environmental ethics	Address 792 W. Higl County Walton	htower Tr	Resource Use Date of Const Iouse Type	Residential: Single Family Dwelling ruction 1965-1974 Ranch
			Barn Type Church Type Commercial T School Type Structural Sys	
		F V V	Roof (Exterior Clade Foundation (Porch I Vindows I	Colonial Revival Gable: side ding Brick: running bond Concrete slab Portico Double hung sash: 6/6 No chimney observed
Preliminary A		Status - Listed	lterations	Applicable Criteria
Not E	ligible	Not listed		с





Resource ID SC-208

Address 701 W. Hightower Tr


County Walton



NARGHIS ID 240519

Resource Type Building **Resource Use** Residential: Single Family Dwelling Date of Construction 1965-1974 Ranch **House Type** Barn Type **Church Type Commercial Type School Type** Post and Beam Structural System Style No academic style Roof Gable: side **Exterior Cladding** Brick: running bond Foundation Concrete slab Porch Portico Windows Double hung sash, 6/6 Chimney No chimney observed Alterations Enclosed carport

Preliminary Assessment	Status - Listed	Applicable Criteria	
Not Eligible	Not listed	С	



Social Circle Historic Resource	
Resource ID SC-210 Resource Type Building	
Address 661 W. Hightower Tr bisorie prevation B Address 661 W. Hightower Tr Date of Construction 1965-1974	welling
Henry planning + design B County Walton House Type Ranch	
Barn Type	
Church Type	
Commercial Type	
School Type	
Structural System Post and Beam	
Style No academic style	
Roof Gable: side	
Exterior Cladding Brick: running bon	d
Foundation Concrete slab	
Porch Front Portico	
Windows Double hung sash: 6/6, 8/1	
Center ridgeline: brick	
Alterations	
Preliminary Assessment Status - Listed Applicable Criteria	
Not Eligible Not listed C	

	Social Circle Historic	c Resource	NARGHIS ID	9 240525	
	Resource ID SC-211 Address 631 W. Hight County Walton		Resource TypeBuildingResource UseResidential: Single Family DDate of Construction1965-1970House TypeRanchBarn TypeChurch TypeChurch TypeSchool TypeSchool TypeStructural SystemStyleNo academic styleRoofGable: side		
			Porch S Windows D Chimney N	ling Brick: running bond Continuous: brick Stoop: front Double-hung sash: 6/6 No chimney observed inclosed carport, replacement materials	
Preliminary A Not El		Status - Listed Not listed		Applicable Criteria C	
	Social Circle Historic	Resource	NARGHIS ID	9 240527	
J J J	Basaurea ID SC 212		Pacouroo Type	- Building	

Resource ID SC-212

Address 478 Hightower Tr


County Walton

C E⁺D




Resource Type Building **Resource Use** Residential: Single Family Dwelling Date of Construction 1965-1974 Ranch House Type Barn Type Church Type **Commercial Type** School Type Structural System Post and Beam Style No academic style Roof Gable: cross **Exterior Cladding** Brick: running Foundation Brick; Concrete Porch Verandah; Recessed; Portico; Carport Windows Jalousie; Chicago Chimney Off-center within roof surf: brick Alterations Enclosed carport

F	Preliminary Assessment	Status - Listed	Applicable Criteria	
	Not Eligible	Not listed	С	



Social Circle Historio	c Resource	NARGHIS ID 240538
Resource ID SC-214		Resource Type Building
Address 308 Hickory	Dr	Resource Use Residential: Single Family Dwelling Date of Construction 1930-1939
Phistoric preservation methods Environmental ethics County Walton		House Type Bungalow: front gable
		Barn Type
	to the Ald and	Church Type
	and the second second	Commercial Type
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	School Type
	S 2	Structural System Balloon frame
		Style Craftsman
	S en	Roof Gable: front
		Exterior Cladding Wood: board and batten; novelty
		Foundation Continuous: brick
		Porch Recessed: front
		Windows Double hung sash: 4/4; Jalousie
	and the second se	Chimney Center ridgeline: brick
the state of the s		Alterations
Preliminary Assessment	Status - Listed	Applicable Criteria
Not Eligible	Not listed	A, C






Address 322 Hickory Dr

County Walton



NARGHIS ID 240542 **Resource Type** Building **Resource Use** Residential: Single Family Dwelling Date of Construction 1930-1939 Bungalow: front gable **House Type** Barn Type **Church Type Commercial Type School Type** Structural System Balloon frame Craftsman Style Roof Gable: front Exterior Cladding Wood: board and batten; novelty Foundation Continuous: brick Porch Recessed Windows Double hung sash: 4/4 Chimney Center ridgeline: brick Alterations Replacement materials

Preliminary Assessment	Status - Listed	Applicable Criteria	
Not Eligible	Not listed	С	



	Social Circle Histori	c Resource	NARGHIS ID 240549		
V OF CI	Resource ID SC-218		Resource Type Building		
bistoric preservation of the environmental ethics	Address 334 Hickory County Walton	Dr	Resource UseResidential: Single Family DwellingDate of Construction1930-1939House TypeBungalow: front gable		
			Barn Type Church Type Commercial Type		
1			School Type Structural System Balloon frame		
			StyleCraftsmanRoofGable: front		
			Exterior Cladding Wood: board and batten; novelty Foundation Continuous: brick Porch Recessed		
			WindowsDouble hung sash: 4/4; JalousieChimneyCenter ridgeline: brick		
			Alterations Replacement materials		
Preliminary A Not Eli		Status - Listed Not listed	Applicable Criteria C		



Resource ID SC-220

Address 333 Hickory Dr

County Walton

C E⁺D




Resource Type Building **Resource Use** Residential:Single Family Dwelling Date of Construction 1930-1939 Side gable cottage **House Type** Barn Type **Church Type Commercial Type School Type** Structural System Balloon frame Style No academic style Gable: cross Roof **Exterior Cladding** Synthetic siding: asbestos Foundation Vontinuous: concrete block Porch Recessed Windows Double hung sash: 1/1 Chimney Off center within roof surface: brick Alterations Replacement materials

 Preliminary Assessment
 Status - Listed
 Applicable Criteria

 Not eligible
 Not listed
 C

	Social Circle H	istoric Resource		N	IARGHIS I	D 2408	562	
OF ENVIR	Resource ID) SC-221		R	esource Typ	pe Bu	ilding	
C E+D	Address 359	9 Hickory Dr			lesource Us	•	esidential: Single family	dwelling
ndscape architecture T istoric preservation PE nv. planning + design SC	County Walt	ton			ate of Const		n ¹⁹⁵⁵⁻¹⁹⁶⁴ anch	
nvironmental ethics 🕇				в	louse Type Barn Type			
N.Stalow			and the second		hurch Type			
and the second	1	A Del			ommercial 1	Туре		
			and the second second	S	chool Type			
			and the second second	s	tructural Sy	stem	Post and beam	
				s	tyle	No acad	lemic style	
and a state				R	loof	Hip		
			A THE	E	xterior Clad	ding	Wood: weatherboard	; Brick: runr
				F	oundation	Continu	ous: Brick	
	The second	and the second second		P	orch	Portico		
	Area and			v	Vindows	Double	hung sash: 6/6	
				c	himney	No chim	iney observed	
			Courses and		-	Rear Ad	ldition	
eliminary As			Status - Listed			Ар	plicable Criteria	
Not Elig	IDIE		Not listed				С	



Resource Ty	pe Building		
Resource Us	se Commercial: Single retail		
Date of Cons	struction 1885-1894		
House Type			
Barn Type			
Church Type)		
Commercial	Type Commercial Block: multiple retail		
School Type			
Structural S	ystem Unknown		
Style	Folk Victorian		
Roof	Partial parapet		
Exterior Cla	dding Stucco		
Foundation	Concrete		
Porch	No porch		
Windows	Fixed		
Chimney	No chimney observed		
Alterations	Replacement materials		

Preliminary Assessment	Status - Listed	Applicable Criteria	
Not Eligible	Listed	С	



Preliminary Assessment	Status - Listed	Applicable Criteria	
Eligible	Listed	С	




Building **Resource Type** Commercial: Single Retail **Resource Use** Date of Construction 1885-1894 House Type Barn Type **Church Type** Commercial Block: multiple retail **Commercial Type** School Type Brick bearing **Structural System** Folk Victorian Flat **Exterior Cladding** Brick: common bond Foundation Unknown Porch No porch observed Fixed Windows No chimney observed Chimney Alterations

Preliminary Assessment Eligible Status - Listed


Applicable Criteria




	Social Circle Historic Resource		NARGHIS ID 240587		
95 40 .	Resource ID SC-227		Resource Type Building		
	Address 132 S Cherokee Rd County Walton		Resource Use Religious: Church		
N landscape architecture N N historic preservation D H env. planning + design S H environmental ethics S			Date of Construction 1885-1894		
environmental ethics			House Type		
			Barn Type		
			Church Type		
			Commercial Type Commercial Block: multiple retail		
			School Type Structural System Brick bearing		
	Alan Change be William				
	132 S. Cherokee		Style Folk Victorian Roof Parapet		
			Exterior Cladding Brick: common bond		
			Foundation Unknown		
			Porch No porch		
			Windows Fixed		
			Chimney No chimney observed		
	The second s		Alterations		
Preliminary A	ssessment	Status - Listed	Applicable Criteria		
Eligi		Listed	C		
	Social Circle Historic Resource		NARGHIS ID 65148		
OLLEGE OF ENV	Resource ID SC-228		Resource Type Building		
	Address 136 Cherokee St		Resource Use Commercial: Single Retail		
landscape architecture +	Address 136 Cherokee St		Date of Construction 1885-1894		
H env. planning + design Sign H environmental ethics	County Walton		House Type		
		1	Barn Type		
			Church Type		
			Commercial Type Commercial Block: Multiple retail		
			School Type		
	MIN A		Structural System Brick bearing Style Folk Victorian		
			Roof Parapet		
			Exterior Cladding Brick: common bond		
			Foundation Brick; Stone: continuous		
			Porch No porch		
			Windows Fixed		
			Chimney No chimney observed		
			Alterations Replacement materials		
Preliminary A	ssessment	Status - Listed	Applicable Criteria		
Eligi		Listed	с		



EoRGIA	Social Circle Histori	c Resource	NARGHIS I	□ 240377
19 40 LL OF GE	Resource ID SC-230		Resource Typ	pe Building
C E+D landscape architecture	Address 292 S. Chero	okee Rd	Resource Use	e Residential: Single Family Dwelling truction 1920-1929
D historic preservation D H env. planning + design S H environmental ethics R			House Type	Bungalow: cross gable
			Barn Type	
S (14)			Church Type	
			Commercial	Туре
			School Type	
		1 1 1 4	Structural Sy	
			- ,	Craftsman
			Roof	Complex
			Exterior Clad	ding Synthetic Siding: vinyl
Sec.			Foundation	Continuous: brick
	The second s		Porch	Verandah
			Windows	Double hung sash: 6/6
Sec. 1		and the second second	Chimney	No chimney observed
		and the second	Alterations	Replacement materials
Preliminary	/ Assessment	Status - Listed		Applicable Criteria
	igible	Listed		C
] [





Address 637 N Cherokee Rd


County Walton



NARGHIS ID 240591 **Resource Type** Building **Resource Use** Residential: Single Family Dwelling Date of Construction 1920-1929 Double pen **House Type** Barn Type **Church Type Commercial Type School Type** Structural System Balloon frame Style No academic style Roof Gable: side **Exterior Cladding** Wood: weatherboard Foundation Pier with infill: brick Porch Verandah

Windows Double hung sash: 6/6 Chimney No chimney observed Alterations Replacement materials, addition

Preliminary Assessment Status - Listed **Applicable Criteria** Not Eligible Not listed С



	Social Circle Historic Resource Resource ID SC-234		NARGHIS ID 240609
9 JO AL			Resource Type Building
CE+D landscape architecture + D historic preservation = D env. planning + design S	Address 681 N Cherc	okee Rd	Resource Use Commercial: Single Retail Date of Construction 1955-1964
Ë environmental ethics 2	County Walton		House TypeRanchBarn TypeChurch TypeCommercial TypeSchool TypeSchool TypeStructural SystemBalloon frameStyleNo academic styleRoofHipExterior CladdingBrick: running bondFoundationContinuous: brickPorchStoop: frontWindowsDouble hung sash: 2/2ChimneyNo chimney observed
			Alterations Carport enclosed, replacement materials
Preliminary A Not El		Status - Listed Not listed	Applicable Criteria C







Resource Type Building Resource Use Residential: Single family dwelling Date of Construction 1940-49 House Type Side gable cottage Barn Type Church Type Commercial Type School Type School Type Structural System Structural System Balloon frame Style No academic style Roof Gable: cross Exterior Cladding Synthetic Siding: vinyl Foundation Brick: continuous Porch Verandah; Portico Windows Double hung sash: 3/1 Chimney Off-center ridgeline: brick Alterations Addition, replacement materials

 Preliminary Assessment
 Status - Listed
 Applicable Criteria

 Not Eligible
 Not listed
 C




	Social Circle Historic	Resource	NARGHIS ID 240618
OF ENVIR	Resource ID SC-238 Address 903 N Cherokee Rd		Resource Type Building
Landscape architecture			Resource Use Residential: Single family dwelling Date of Construction 1940-1949
 D historic preservation DE H env. planning + design SG H environmental ethics 	County Walton		House Type Bungalow: cross gable
			Barn Type Church Type Commercial Type
	C TO MAND		School Type Structural System Post and Beam
			Style No academic style
			Roof Gable: cross
			Exterior Cladding Synthetic Siding: asbestos
			Foundation Continuous: concrete block
And and a second se			Porch Portico
		and the second	Windows Double hung sash: 1/1, 2/2
	Participation - and		Chimney Off-center ridgeline: brick
			Alterations Rear addition, replacement materials
Preliminary A Not Eli		Status - Listed Not listed	Applicable Criteria C





NARGHIS	^{ID} 240620
Resource Ty	pe Building
Resource Us	Residential: Single Family Dwelling
Date of Cons	struction 1920-1920
House Type	Bungalow: side gable
Barn Type	
Church Type	
Commercial	Туре
School Type	
Structural Sy	stem Balloon frame
Style	No academic style
Roof	Gable: side
Exterior Clac	ding Synthetic Siding: asbestos
Foundation	Continuous: concrete
Porch	Stoop
Windows	Double hung sash: 6/6
Chimney	No chimney observed
Alterations	


Preliminary Assessment	Status - Listed	Applicable Criteria	
Not Eligible	Not listed	С	



Social Circle Historic	Resource	IARGHIS ID 240623
Resource ID SC-242	R	Resource Type Buuilding
Address 1081 N Cherce historic preservation of environmental ethics of County Walton	Dkee Rd D	Resource Use Residential: Single family dwelling Date of Construction 1910-1919 House Type Georgian cottage Barn Type
	C S S S R E	Church Type Commercial Type School Type Structural System Balloon frame Style No academic style Roof Gable: side Exterior Cladding Synthetic Siding: vinyl
		FoundationPier with infill: brickPorchVerandah: frontVindowsDouble hung sash: 1/1, 2/2ChimneyGable end interior: stuccoed masonryNiterationsMultiple additions
Preliminary Assessment Not Eligible	Status - Listed Not listed	Applicable Criteria C








	Social Circle Historic Resource		NARGHIS ID 65159
OF GE	Resource ID SC-246		Resource Type Building
C E+D Indscape architecture historic preservation DB env. planning + design DB env. planning + design DB env. planning + design DB env. planning + design DB	Address 192 E Highto County Walton	ower Trl	Resource UseResidential: Single Family DwellingDate of Construction1920-1929House TypeBungalow: cross gable
			House TypeDuriguow: closs gubicBarn TypeChurch TypeCommercial TypeSchool TypeStructural SystemBalloon frameStyleCraftsmanRoofGable: crossExterior CladdingWood: weatherboardFoundationUnknownPorchPorticoWindowsDouble hung sash : 24/1ChimneyOff-center within roof surf; Gable end exterior:brickAlterations
Preliminary A Eligit		Status - Listed Listed	Applicable Criteria C




No academic style Roof Gable: side **Exterior Cladding** Brick: running bond Foundation Continuous: brick Porch Stoop Windows Double hung sash: 2/2; Fixed Chimney No chimney observed Alterations Enclosed garage

Preliminary Assessment Status - Listed **Applicable Criteria** Not Eligible Not listed С




Social Circle H	listoric Resource	NARGHIS ID 240608
Resource ID SC-	250	Resource Type Building
Address 210 Ho County Walton	olly Ave	Resource Use Residential: Single family dwelling Date of Construction 1940-1949 House Type Bungalow: side gable Barn Type Church Type Commercial Type School Type Structural System Balloon frame
		StyleNo academic styleRoofGable: steppedExterior CladingBrick: running bondFoundationContinuous: brickPorchStoop: frontWindowsDouble hung sash: 2/2; FixedChimneyOff-center within roof surf: brickAlterationsReplacement materials, additions
Preliminary Assessment Not Eligible	Status - Listed Listed	Applicable Criteria C






NARGHIS ID 240614					
Resource Ty	pe Building				
Resource Us	Residential: Single Family Dwelling				
Date of Cons	struction 1900-1909				
House Type	Gabled ell cottage				
Barn Type					
Church Type					
Commercial	Туре				
School Type					
Structural Sy	stem Balloon frame				
Style	No academic style				
Roof	Gable: cross				
Exterior Clac	Iding Synthetic Siding: vinyl				
Foundation	Continuous: concrete block				
Porch	Verandah				
Windows	Double hung sash: 2/2, 1/1				
Chimney	Center ridgeline: brick				
Alterations	Additions				

Preliminary Assessment	Status - Listed	Applicable Criteria	
Not eligible	Listed	С	



	Social Circle Histori	c Resource	NARGHIS	^{ID} 240629
2 9 9 V	Resource ID SC-254		Resource Ty	pe Building
Landscape architecture	Address 422 Sweetgu	um St	Resource Us Date of Cons	Residential: Single Family Dwelling struction 1960-1969
Henv. planning + design Sign Henv. planning + design Sign Henvironmental ethics	County Walton		House Type	Ranch
5.00		a state of the	Barn Type Church Type	
			Commercial	
			School Type	
		and the second	Structural Sy	stem Post and Beam
			Style	No academic style
			Roof	Hip
		Alter a	Exterior Clac	•
				Continuous: brick
	- Langers		Porch	Stoop: front
			Windows	Double hung sash: 2/2
			Chimney	No chimney observed
			Alterations	Replacement materials
Preliminary A	ssessment	Status - Listed		Applicable Criteria
Not Eli		Not listed		с





Resource ID SC-256

Address 396 Sweetgum St


County Walton




NARGHIS ID 240631

Resource Type Building **Resource Use** Residential: Single family dwelling Date of Construction 1965-1974 Ranch **House Type** Barn Type **Church Type Commercial Type School Type** Post and Beam Structural System Style No academic style Roof Gable: side **Exterior Cladding** Brick: running bond Foundation Continuous: concrete Porch Stoop Windows Double hung sash: 2/2 Chimney No chimney observed Alterations

Preliminary Assessment	Status - Listed	Applicable Criteria	
Not Eligible	Not listed	С	



OF GEORGIA	Social Circle Histori	c Resource	NARGHIS	^{ID} 240637
D 10 Y	Resource ID SC-258		Resource Ty	
the order of the o	Address 369 Sweetgi County Walton	um St	Resource Us Date of Cons House Type Barn Type Church Type Commercial	struction 1960-1969 Ranch
			School Type Structural Sy Style Roof Exterior Clac Foundation Porch Windows Chimney Alterations	ystem Balloon Frame No academic style Hip
Preliminary A Not Eli		Status - Listed Not listed		Applicable Criteria C





Resource ID SC-260

Address 402 East Willow Dr


County Walton



NARGHIS ID 240641

Resource Type Building **Resource Use** Residential: Single Family Dwelling Date of Construction 1930-1939 Bungalow: hip **House Type** Barn Type **Church Type Commercial Type School Type** Post and Beam Structural System No academic style Style Roof Hip **Exterior Cladding** Wood: weatherboard Foundation Pier with infill; brick Porch Verandah Windows Double hung sash: 2/2, 6/6 Chimney No chimney observed Alterations Rear addition

Preliminary Assessment	Status - Listed	Applicable Criteria	
Not Eligible	Not listed	С	



	Social Circle Histori	c Resource	NARGHIS ID 240644
OF ENVIR	Resource ID SC-262		Resource Type Building
LIST CE E+D Indiscape architecture Historic preservation He environmental ethics	Address 460 Oak St County Walton		Resource UseResidential: Single Family DwellingDate of Construction1960-1969House TypeRanchBarn TypeChurch TypeCommercial Type
			School Type Structural System Post and Beam Style No academic style Roof Hip Exterior Cladding Brick: running bond; Synthetic Siding: vinyl Foundation Continuous: brick, concrete Porch Stoop
Parliminan	A		Windows Double hung sash: 2/2 Chimney No chimney observed Alterations Replacement materials, addition
-	Assessment Eligible	Status - Listed Not listed	Applicable Criteria C

	Social Circle Historic Resource		NARGHIS II	D 240645
COLLEGE OF ENVIR	Resource ID SC-263		Resource Typ	e Building
Landscape architecture	Address 401 Oak St		Resource Use	Residential: Single Family Dwelling ruction 1960-1969
 D historic preservation D env. planning + design Sic environmental ethics N 	County Walton		House Type	Ranch
			Barn Type	
			Church Type	
STATE AND			Commercial T	Гуре
	Contraction of the second second	1 Battan Car	School Type	
			Structural Sys	stem Post and beam
			Style	No academic style
1			Roof	Hip
11 × 1			Exterior Clade	ding Brick: running bond
			Foundation	Continuous: brick, concrete
			Porch	Stoop
			Windows	Double hung sash: 2/2
			Chimney	No chimney observed
			Alterations	Replacement materials
			_	
Preliminary A	ssessment	Status - Listed		Applicable Criteria

Not listed

C E+D histric prevavion env: planing + design

Not Eligible

Social Circle Historic Resource

Resource ID SC-264

Address 387 Oak St

County Walton



NARGHIS ID 240646

Resource Type Building **Resource Use** Residential: Single Family Dwelling Date of Construction 1965-1974 Ranch House Type Barn Type Church Type **Commercial Type** School Type Structural System Post and beam Style No academic style Roof Gable: stepped **Exterior Cladding** Brick: running bond Foundation Continuous: brick, concrete Porch Verandah Windows Double hung sash: 2/2, Chicago Chimney No chimney observed Alterations Replacement materials, enclosed carport

С

Preliminary Assessment	Status - Listed	Applicable Criteria	
Not Eligible	Not listed	С	



Resource Type	Building			
Resource Use	Residential: Single Family Dwelling			
Date of Constru	ction ¹⁹⁶⁰⁻¹⁹⁶⁹			
House Type	Ranch			
Barn Type				
Church Type				
Commercial Typ	e			
School Type				
Structural Syste	m Post and beam			
Style No :	academic style			
Roof Gat	ole: side			
Exterior Claddin	g Brick: Running Bond			
Foundation Cor	tinous: brick, concrete block			
Porch Vera	Verandah			
Windows Dou	Double hung sash: 2/2			
Chimney No o	No chimney observed			
Alterations Enc	losed carport, enclosed porch, addition			

Preliminary Assessment Not Eligible Status - Listed

Applicable Criteria



 Preliminary Assessment
 Status - Listed
 Applicable Criteria


 Not Eligible
 C

	Social Circle Historic Resource	NARGHIS ID 240649
D JO A	Resource ID SC-267	Resource Type Building
	Address 351 Oak St	Resource Use Residential: Single Family Dwelling
D historic preservation D		
H env. planning + design SG H environmental ethics N	County Walton	House Type Ranch
		Barn Type
		Church Type
		Commercial Type
		School Type
100		Structural System Post and beam
		Style No academic style
		Roof ^{Hip}
		Exterior Cladding Brick: running bond
	and the second sec	Foundation Continuous: brick, concrete block
and the second		Porch Stoop
		Windows Double hung sash: 2/2; Jalousie
and the second		Chimney No chimney observed
		Alterations
Preliminary A		d Applicable Criteria
Potentially	eligible Not listed	С
		NARGHIS ID 240663
	Social Circle Historic Resource	
J JO JO FENVI	Resource ID SC-268	Resource Type Site
	Address 1 mile east of junction St Rte 11 and Cannon Rd	Resource Use Religious: funerary
N landscape architecture 4		Date of Construction ¹⁹⁰⁰
H env. planning + design S E environmental ethics	County Walton	House Type



Resource TypeSiteResource UseReligious: funeraryDate of Construction1900House Type1900Barn Type1900Church Type1900Commercial Type1900School Type1900Structural System1900Style1900Roof1900Exterior Cladding1900Foundation1900Porch1900Windows1900ChimneyAlterationsAlterationsActive use cemetery

Preliminary Assessment	Status - Listed	Applicable Criteria
Not Eligible	Not listed	C, D




	Social Circle Historic Resource		NARGHIS ID 240469
OF ENVIR	Resource ID SC-270		Resource Type Building
Landscape architecture	Address 1180 N. Cherokee	Rd.	Resource Use Residential: Single Family Dwelling Date of Construction 1960-1969
D historic preservation D H env. planning + design S H environmental ethics S	County Walton		House Type Side Gable Cottage
		ça:	Barn Type
		10.200	Church Type
			Commercial Type
			School Type
			Structural System Post and beam
			Style No academic style
			Roof Hip
i and i a		and the second se	Exterior Cladding Synthetic siding: vinyl
			Foundation Continuous: brick
		1	Porch Portico; verandah
			Windows Double hung sash: 2/2
		I ALLENSON	Chimney Center: brick
			Alterations Rear hip addition
Preliminary A	ssessment	Status - Listed	Applicable Criteria
Not Eli	gible	Not listed	C
		L	

OF GEORGIA	Social Circle Historic Resource	се	NARGHIS ID 240915
E OF ENVIR	Resource ID SC-271		Resource Type Building
Landscape architecture	Address 708 Beech Ave		Resource Use Residential: Single Family Dwellir Date of Construction 1965-1974
 historic preservation env. planning + design environmental ethics 	County Walton		House Type Ranch
			Barn Type
1000	A Star School		Church Type
			Commercial Type
			School Type
	In the second state		Structural System Post and beam
			Style No academic style
			Roof Gable: side
			Exterior Cladding Brick: running bond
			Foundation Continous: Brick
		and the state of the second	Porch Stoop
Marrie L.	Time Contract Stands	and a start of the	Windows Double hung sash: 2/2
Star of			Chimney No chimney observed
184 AV	A CONTRACTOR OF THE OWNER OF THE		Alterations
Preliminary	Assessment	Status - Listed	Applicable Criteria
	ligible	Not listed	c c

Social Circle Historic Resou	nce NARGHIS ID 240470
Resource ID SC-272 Address 1328 Boxwood County Walton	Resource Type Building Resource Use Residential: Single Family Dwelling
	School Type Structural System Balloon frame Style No academic style Roof Hip Exterior Cladding Brick: common bond Foundation Continuous: Brick Porch Verandah Windows Double hung sash: 2/2 Chimney No chimney observed Alterations Altered porch and front entry
Preliminary Assessment	Status - Listed Applicable Criteria

Preliminary Assessment	Status - Listed	Applicable Criteria	
Not Eligible	Not listed	С	






Resource Ty	pe Building
Resource Us	e Residential: Single Family Dwelling
Date of Cons	struction ¹⁹⁶⁰⁻¹⁹⁶⁹
House Type	Ranch
Barn Type	
Church Type	
Commercial	Туре
School Type	
Structural Sy	/stem Post and beam
Style	No academic style
Roof	Нір
Exterior Clac	ding Brick: common bond
Foundation	Continuous: Brick
Porch	Stoop
Windows	Double hung sash: 2/2
Chimney	No chimney observed
Alterations	

Preliminary Assessment	Status - Listed	Applicable Criteria	
Potentially Eligible	Not listed	С	

	Social Circle Historic Resource		NARGHIS I) 240473
V OF GE	Resource ID SC-275		Resource Type	e Building
Iandscape architecture	Address 332 Boxwood St		Resource Use	Residential: Single Family Dwelling ruction ¹⁹⁶⁰⁻¹⁹⁶⁹
 A historic preservation B env. planning + design E environmental ethics 	County Walton		House Type	Ranch
			Barn Type	
1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1		- aliates	Church Type	
State State	AND THE REAL PROPERTY OF	1 Sugar	Commercial T	ype
The second second			School Type	
			Structural Sys	tem Post and beam
		the state of the second se	=	No academic style
				Gable: side
1 STARA		Contraction of the local division of the loc	Exterior Clado	ling Brick: running bond
				Continuous: Brick
		the state of the s		Stoop
				Double hung sash: 2/2
and the second				No chimney observed
			······	Enclosed carport
			Alterations	·
Preliminary As	ssessment	Status - Listed		Applicable Criteria
Not Elic		Not listed		C





Resource ID SC-277

Address 304 Boxwood St

County Walton



NARGHIS ID 240475

Building **Resource Type** Residential: Single Family Dwelling **Resource Use** Date of Construction ¹⁹⁶⁰⁻¹⁹⁶⁹ Ranch House Type Barn Type **Church Type Commercial Type** School Type Post and beam **Structural System** No academic style Style Gable: side Roof **Exterior Cladding** Brick: running bond Foundation Continuous: Brick Porch Stoop Double hung sash: 2/2 Windows No chimney observed Chimney Alterations

Preliminary Assessment Not Eligible Status - Listed Not listed

Applicable Criteria



Social Circle Historic Resource

Resource ID SC-278

Address 298 S. Cherokee Rd

County Walton



NARGHIS ID 240376

Resource Ty	pe Building
Resource Us	se Residential: Single Family Dwelling
Date of Cons	struction ¹⁹²⁰⁻¹⁹²⁹
House Type	Bungalow: side gable
Barn Type	
Church Type)
Commercial	Туре
School Type	
Structural S	ystem Balloon frame
Style	Craftsman
Roof	Gable: side
Exterior Cla	dding Wood: weatherboard
Foundation	Continuous: Brick
Porch	Portico
Windows	Double hung sash: 6/6
Chimney	Off center ridgeline: brick
Alterations	

 Preliminary Assessment
 Status - Listed
 Applicable Criteria

 Eligible
 Listed
 C

	Social Circle Historic Resource		NARGHIS ID 240477
OF ENV	Resource ID SC-279		Resource Type Building
CE+D Iandscape architecture + historic preservation env. planning + design sig	Address 275 Poplar Ave		Resource UseResidential: Single Family DwellingDate of Construction1970-1979House TypeRanch
			Barn Type Barn Type Church Type Commercial Type School Type Structural System Post and beam Style No academic style Roof Hip Exterior Cladding Brick: running bond Foundation Continuous: Brick Porch Portico Windows Double hung sash: 6/6 Chimney No chimney observed Alterations Fore the state of
Preliminary A Not Eli		Status - Listed Not listed	Applicable Criteria C
	Social Circle Historic Resource		NARGHIS ID 240479

A DECEMBENT OF ENVIRONMENT OF ENVIRO

Resource ID SC-280

Address 295 Poplar Ave


County Walton



Resource Ty	pe Building
Resource Us	e Residential: Single Family Dwelling
Date of Cons	struction ¹⁹⁶⁰⁻¹⁹⁶⁹
House Type	Ranch
Barn Type	
Church Type	
Commercial	Туре
School Type	
Structural Sy	/stem Post and beam
Style	No academic style
Roof	Gable: cross
Exterior Clac	Iding Synthetic siding: Vinyl siding
Foundation	Brick
Porch	Recessed
Windows	Double hung sash: 6/6
Chimney	No chimney observed
Alterations	Replacement materials


Preliminary Assessment	Status -	Listed	Applicable Criteria
Not Eligible	Not lis	ted	с





Resource Ty	pe Building
Resource Us	Residential: Single family dwelling
Date of Cons	struction ¹⁹¹⁰⁻¹⁹¹⁹
House Type	Gabled-ell cottage
Barn Type	
Church Type)
Commercial	Туре
School Type	
Structural S	ystem Balloon frame
Style	No academic style
Roof	Gable: cross
Exterior Cla	dding Synthetic siding: Vinyl
Foundation	Pier with infill: brick
Porch	Verandah
Windows	Double hung sash: 6/6
Chimney	Center: brick
Alterations	Addition; replacement materials

Preliminary Assessment Not Eligible Status - Listed Not listed Applicable Criteria





Resource ID SC-284

Address 608 Beech Ave


County Walton




Resource Type	Building
Resource Use	Residential: Single family dwelling
Date of Construc	tion ¹⁹⁵⁵⁻¹⁹⁶⁴
House Type	Bungalow: side gable
Barn Type	

incase iype		0	0
Barn Type			
Church Type	•		
Commercial	Туре		
School Type			
Structural Sy	/stem	Balloon fra	me
Style	No acade	emic style	
Roof	Gable: si	de	
Exterior Clac	ding	Synthetic s	iding: Vinyl
Foundation	Continuo	us: concrete	e block
Porch	Stoop		
Windows	Double h	ung sash: 1	/1
Chimney	Off-cente	r ridgeline: I	orick
Alterations	Addition;	enclosed ve	erandah

Preliminary Assessment	Statu	is - Listed	Applicable Criteria	
Not Eligible	N	ot listed	с	






Building
Residential: Single family dwelling
uction ¹⁹⁴⁵⁻¹⁹⁵⁴
Bungalow: front gable
ре
em Balloon frame
o academic style
able: front
ng Synthetic siding: Masonite
ontinuous: concrete block
erandah
ouble hung sash: 4/4
o chimney observed
eplacement materials, addition

 Preliminary Assessment
 Status - Listed
 Applicable Criteria

 Not Eligible
 Not listed
 C





Resource ID SC-288 Corinth Baptist Church

Address 373 Dogwood Ave


County Walton



NARGHIS ID 240913

Resource Type Building **Resource Use** Religious: Church Date of Construction 1960-1969 Ranch **House Type** Barn Type **Church Type Commercial Type School Type** Balloon frame Structural System Style No academic style Roof Gable: side **Exterior Cladding** Stucco Foundation Continuous: concrete block Porch Portico Windows Double hung sash: 6/6 Chimney No chimney observed Alterations Integrated carport

Preliminary Assessment	Status - Listed	Applicable Criteria	
Not Eligible	Not listed	С	




Building **Resource Type** Residential: Single family dwelling **Resource Use** Date of Construction ¹⁹²⁵⁻¹⁹³⁴ Bungalow: front gable House Type Barn Type **Church Type Commercial Type** School Type Balloon frame Structural System Craftsman Style Gable: front Roof **Exterior Cladding** Synthetic siding: vinyl Foundation Continuous: concrete block Porch Verandah Double hung sash: 6/6 Windows Gable end exterior: brick Chimney Alterations Addition; replacement materials

Preliminary Assessment Not Eligible

Status - Listed Not listed

Applicable Criteria С




Address 285 Jones Dr

County Walton



Resource Ty	pe Building
Resource Us	Residential; Single family dwelling
Date of Cons	struction ¹⁹¹⁰⁻¹⁹¹⁹
House Type	Single pen
Barn Type	
Church Type)
Commercial	Туре
School Type	
Structural S	ystem Balloon frame
Style	No academic style
Roof	Gable: side
Exterior Cla	dding Wood: weatherboard
Foundation	Continuous: concrete block
Porch	Stoop
Windows	Double hung sash: 6/6
Chimney	Gabled-interior: brick
Alterations	

Preliminary Assessment	Status - Listed	Applicable Criteria	
Eligible	Not listed	С	





Resource ID SC-292

Address 282 Jones Dr


County Walton




NARGHIS ID 240923

Resource Type Building **Resource Use** Residential: Single family dwelling Date of Construction 1910-1919 Single pen **House Type** Barn Type **Church Type Commercial Type School Type** Balloon frame Structural System Style No academic style Roof Gable: side **Exterior Cladding** Wood: weatherboard Foundation Continuous: concrete Porch Stoop Windows Double hung sash: 9/9 Chimney No chimney observed Alterations Chimney removed; rear addition

Preliminary Assessment	Status - Listed	Applicable Criteria	
Not Eligible	Not listed	С	





Resource Ty	pe Building
Resource Us	Residential: Single family dwelling
Date of Cons	struction ¹⁹¹⁰⁻¹⁹¹⁹
House Type	Single pen
Barn Type	
Church Type)
Commercial	Туре
School Type	
Structural Sy	ystem Balloon frame
Style	No academic style
Roof	Gable: side
Exterior Cla	dding Synthetic siding: Masonite
Foundation	Continuous: concrete
Porch	Stoop
Windows	Double hung sash: 6/6, 4/4
Chimney	No chimney observed
Alterations	Replacement materials, chimney removed

 Preliminary Assessment
 Status - Listed
 Applicable Criteria

 Not eligible
 Not listed
 C

	Social Circle Historic Resource		NARGHIS ID	240926
E OF ENVIE	Resource ID SC-295		Resource Type	Building
Landscape architecture +	Address 312 Jones Dr		Resource Use Date of Constru	Residential: Single family dwelling 1955-1964
H env. planning + design EGG environmental ethics	County Walton		House Type	Ranch
			Barn Type	
		A CONTRACTOR OF THE OWNER OF THE	Church Type	
			Commercial Typ	De
			School Type	
			Structural Syste	em Post and beam
and the same of the same			Style No	academic style
			Roof Ga	ble: side
		And and a set of a	Exterior Claddin	ng Brick: running bond
		ALL	Foundation Un	known
and a support of the support			Porch Sto	рор
	Contraction and Contraction of Contr		Windows Do	uble hung sash: 2/2
Service -	Contraction of the second second		Chimney No	chimney observed
a proved find	and the second second second second	Red March 199	Alterations Re	placement materials
Preliminary A	Assessment	Status - Listed		Applicable Criteria
Not El	ligible	Not listed		С



Resource ID SC-296


Address Approximately 280 Jones Drive

County Walton



Resource Ty	pe I	Building
Resource Us	e I	Residential: Single family dwelling
Date of Cons	structi	on 1955-1964
House Type	I	Ranch
Barn Type		
Church Type		
Commercial	Туре	
School Type		
Structural Sy	/stem	Post and beam
Style	No ac	ademic style
Roof	Gable	: side
Exterior Clac	lding	Brick: running bond
Foundation	Unkno	own
Porch	Stoop	
Windows	Doubl	e hung sash: 6/6
Chimney	No ch	imney observed
Alterations	Repla	cement materials

Preliminary Assessment	Status - Listed	Applicable Criteria	
Not Eligible	Not listed	С	



The presented environmental ethics	Social Circle Historic Resource	
5 10 YT	Resource ID SC-298	L
Landscape architecture	Address 342 Jones Dr	L
 D historic preservation D = env. planning + design S = environmental ethics S 	County Walton	L
	<image/>	

Resource Ty	/pe Building
Resource U	se Residential: Single family dwelling
Date of Con	struction ¹⁹⁶⁵⁻¹⁹⁷⁴
House Type	Ranch
Barn Type	
Church Type	9
Commercial	Туре
School Type	
Structural S	ystem Post and beam
Style	No academic style
Roof	Hip
Exterior Cla	dding Brick: running bond
Foundation	Continuous: concrete block
Porch	Stoop
Windows	Double hung sash: 2/2
Chimney	No chminey observed
Alterations	Replacement materials

 Preliminary Assessment Not Eligible
 Status - Listed Not listed
 Applicable Criteria C

OF GEORGIA	Social Circle Historic Resou	Irce	NARGHIS ID 240930	
	Resource ID SC-299		Resource Type Building	
Landscape architecture +	Address Approximately	401 Walnut St	Resource Use Residential: Single family d Date of Construction 1960-1969	wellin
 D historic preservation D env. planning + design E environmental ethics 	County Walton		House Type Ranch	
			Barn Type	
			Church Type	
A Sub-			Commercial Type	
	A A A		School Type	
			Structural System Post and beam	
			Style No academic style	
1			Roof ^{Hip}	
			Exterior Cladding Brick: running bond	
			Foundation Continuos: concrete	
	A Company of the second		Porch Obscured	
	and the second		Windows Double hung sash: 2/2	
			Chimney No chimney observed	
			Alterations	
Preliminary	Assessment	Status - Listed	Applicable Criteria	
-	ligible	Not listed	C	



Resource ID SC-300

Address 140 N Cherokee Rd

County Walton



NARGHIS ID 65141 **Resource Type** Building **Resource Use** Residential: Single family dwelling Date of Construction 1900-1909 Queen Anne cottage House Type Barn Type Church Type **Commercial Type** School Type Structural System Balloon frame Style Neoclassical revival Roof Complex Exterior Cladding Wood: Weatherboard Foundation Continuous: concrete block, brick Porch Wrap-around Double hung sash: 1/1; Fixed Windows Chimney No chminey observed Alterations

Preliminary Assessment	Status - Listed	Applicable Criteria	
Eligible	Listed	С	



		_		
	Social Circle Historic Resource		NARGHIS	ID 240327
OF ENVI	Resource ID SC-302		Resource Ty	r pe Building
	Address 111 N Cherokee Ro	,	Resource Us	Residential: Single family dwelling
A landscape architecture + D historic preservation D		·	Date of Cons	struction ¹⁹¹⁰⁻¹⁹¹⁹
H env. planning + design S environmental ethics	County Walton		House Type	New South cottage
			Barn Type	
E.			Church Type	9
			Commercial	Туре
		A Contraction	School Type	
			Structural Sy	ystem Balloon frame
			Style	Folk victorian
			Roof	Complex
		11 I	Exterior Cla	• , •
			Foundation	Continuous: Brick with stucco
			Porch	Wrap-around
			Windows	Double hung sash: 2/2
- Sugar an			Chimney	Lateral exterior; Off-center within roof
			Alterations	Addition, Replacement materials
Preliminary A		Status - Listed		Applicable Criteria
Eligib	ble	Listed		C

		L		Building
JO ALI	Resource ID SC-303		Resource Ty	he a
	Address Holly St at N Cherok	ee Rd	Resource Us	1005 1011
A historic preservation Personal and the second s	County Walton		Date of Cons	New South cottage
E environmental ethics	County Walton		House Type	New South Cottage
		the second second	Barn Type	
			Church Type	
3162			Commercial	
			School Type	
and the second			Structural Sy	
			Style	No academic style
		6	Roof	Complex
			Exterior Clac	•
			Foundation	Pier with infill: brick
			Porch	Wrap-around
		Annual Property of the Property of the Pro-	Windows	Double hung sash: 2/2
			Chimney	Off-center ridgeline; Off-center within roof sur
			Alterations	
Preliminary A	ssessment	Status - Listed		Applicable Criteria
Eligib	le	Listed		с



Social Circle Historic Resource
Resource ID SC-304

Address 236 N Cherokee Rd


County Walton




NARGHIS ID 240329 Resource Type Building **Resource Use** Residential: Single family dwelling Date of Construction 1950-1959 House Type Ranch Barn Type Church Type **Commercial Type** School Type Structural System Post and beam Style No academic style Roof Hip; Gable Exterior Cladding Brick: common bond; Asbestos Foundation Unknown Porch No porch Windows Double hung sash: 6/1, 4/1; Triple hung sash Chimney Center: brick Replacement materials, multiple additions Alterations

 Preliminary Assessment
 Status - Listed
 Applicable Criteria

 Not Eligible
 Not Listed
 C




	Social Circle Historie	c Resource	NARGHIS	^{ID} 240334
5 JO Y	Resource ID SC-306		Resource Ty	pe Building
	Address 294 N Chero	kee Rd	Resource Us	
Iandscape architecture historic preservation			Date of Cons	struction ¹⁹¹⁷
H env. planning + design Sign H environmental ethics	County Walton		House Type	Georgian House
			Barn Type	
	No. A CARLON AND A CARLON	WELL BA	Church Type	
			Commercial	Туре
			School Type	
			Structural Sy	ystem Balloon frame
			Style	Neoclassical
			Roof	Hip; Pyramidal
RLUE	WILL PROPERTY OF		Exterior Clac	dding Brick: running bond
			Foundation	Continuous
Furth			Porch	Verandah; Balcony
Listan .	A A A		Windows	Double hung sash: 1/1; Fixed
	Contraction of the second seco		Chimney	Off-center ridgeline: brick
		A A A A A A A A A A A A A A A A A A A	Alterations	Rear addition
Preliminary A	ssessment	Status - Listed		Applicable Criteria
Eligit	ble	Listed		C
		ι		





Preliminary Assessment	Status - Listed	Applicable Criteria
Eligible	Listed	С





Resource Ty	pe Building
Resource Us	se Residential: Single family dwelling
Date of Cons	struction ¹⁹²⁰⁻¹⁹²⁹
House Type	Georgian house
Barn Type	
Church Type)
Commercial	Туре
School Type	
Structural S	ystem Balloon frame
Style	Colonial Revival
Roof	Gable: side; Hip
Exterior Cla	dding Brick: running
Foundation	Continuous: brick
Porch	Verandah; Stoop
Windows	Double hung sash: 6/6; Fixed
Chimney	Off-center ridgeline: brick
Alterations	

Preliminary Assessment	Status - Listed	Applicable Criteria	
Eligible	Listed	С	

	Social Circle Historic Resource		NARGHIS ID 240343
OF ENVIRO	Resource ID SC-311		Resource Type Building
C E+D landscape architecture	Address 394 N Cherokee Ro	d	Resource Use Residential: Single family dwelling Date of Construction ¹⁹¹⁰⁻¹⁹¹⁹
Historic preservation D Henv. planning + design S Henvironmental ethics S	County Walton		House Type Georgian cottage
ar 100 20 100			Barn Type
1. 6			Church Type
			Commercial Type
and the second second			School Type
			Structural System Balloon frame
Contraction of the second s			Style Craftsman
			Roof ^{Hip}
			Exterior Cladding Synthetic siding: Asbestos
			Foundation Continuous: brick, concrete block
Charles and			Porch Verandah
			Windows Double hung sash: 2/2
		and the second second	Chimney Off-center within roof surf: brick
			Alterations Replacement materials
Preliminary A		Status - Listed	Applicable Criteria
Eligi	ble	Listed	C



Resource ID SC-312

Address 400 N Cherokee Rd

County Walton



NARGHIS	ID 240344
Resource Ty	pe Building
Resource Us	se Residential: Single family dwelling
Date of Cons	struction ¹⁹¹⁰⁻¹⁹¹⁹
House Type	New South Cottage
Barn Type	
Church Type	9
Commercial	Туре
School Type	•
Structural S	ystem Balloon frame
Style	No academic style
Roof	Gable: front; Hip
Exterior Cla	dding Wood: Weatherboard
Foundation	Continuous: brick
Porch	Wrap-around
Windows	Double hung sash: 1/1; Fixed
Chimney	Off-center ridgeline: brick
Alterations	Rear addition


Preliminary Assessment	Status - Listed	Applicable Criteria	
Eligible	Listed	С	





Resource Ty	pe Building
Resource Us	e Residential: Single family dwelling
Date of Cons	struction ¹⁹²⁵⁻¹⁹³⁴
House Type	Bungalow: cross gable
Barn Type	
Church Type)
Commercial	Туре
School Type	
Structural S	ystem Balloon frame
Style	Craftsman
Roof	Gable: cross
Exterior Cla	dding Wood: Weatherboard
Foundation	Continuous: brick
Porch	Verandah
Windows	Double hung sash: 8/1
Chimney	Off-center ridgeline: brick
Alterations	

Preliminary Assessment	Status - Listed	Applicable Criteria	
Eligible	Listed	С	





Resource ID SC-316


Address 462 N Cherokee Rd


County Walton



NARGHIS	ID 240350
Resource Ty	pe Building
Resource Us	e Residential: single family dwelling
Date of Cons	struction ¹⁹⁰⁵
House Type	New South Cottage
Barn Type	
Church Type	
Commercial	Туре
School Type	
Structural Sy	/stem Balloon frame
Style	Colonial revival
Roof	Gable: front; Pyramidal
Exterior Clad	dding Wood: Weatherboard
Foundation	Continuous: brick
Porch	Wrap-around
Windows	Double hung sash: 1/1; Fixed
Chimney	Off-center ridgeline: brick
Alterations	Rear addition
_	

Preliminary Assessment	Status - Listed	Applicable Criteria	
Eligible	Listed	С	






Resource Ty	pe Building
Resource Us	Residential: Single family dwelling
Date of Cons	struction ¹⁸⁸⁹
House Type	Central hallway
Barn Type	
Church Type	•
Commercial	Туре
School Type	
Structural Sy	ystem Balloon frame
Style	No academic style
Roof	Gable: side
Exterior Cla	dding Wood: Weatherboard
Foundation	Continuous: Brick
Porch	Verandah
Windows	Double hung sash: 2/1
Chimney	Both gable ends: brick
Alterations	Multiple additions

Preliminary Assessment	Status - Listed	Applicable Criteria	
Potentially Eligible	Not listed	С	


	Social Circle Historic Resource	2	NARGHIS ID	240353
TY OF GE	Resource ID SC-319		Resource Type	Building
C E+D landscape architecture	Address 524 N Cherokee R	Rd	Resource Use Date of Constru	Residential: Single family dwellin ction 1900-1909
 historic preservation env. planning + design environmental ethics 	County Walton		House Type	Central hallway
1998			Barn Type	
	Step 1		Church Type	
	and the start		Commercial Typ	e
241		1. E.M. 8. 11 2	School Type	
		and the second	Structural Syste	
			etjie	academic style
日本人			Roof Ga	ble: side
			Exterior Claddin	•
			I oundation	known
				andah
				uble hung sash: 9/9
and the second second			,	h gable ends exterior: stucco
			Alterations Rea	ar addition
Preliminary A	Assessment	Status - Listed		Applicable Criteria
Potentially		Not listed		c




Preliminary Assessment	Status - Listed	Applicable Criteria	
Not Eligible	Not listed	С	



EORGIA	Social Circle Historic Resource		NARGHIS ID 24	0375
The second secon	Resource ID SC-322 Address 304 S. Cherokee R County Walton	Rd.	Resource Use Date of Constructi House Type Barn Type Church Type Commercial Type School Type Structural System Style No ac Roof Flat Exterior Cladding Foundation Contir Porch Reces Windows Doubl Chimney No ch	Commercial: single retail Unknown ademic style Brick: running bond nuous: brick; concrete
Preliminary A Not Eli		Status - Listed Listed	A	pplicable Criteria C



	Social Circle Historic	c Resource	IARGHIS ID 240558		
OF ENVIR	Resource ID SC 324	R	Resource Type Building		
C E + D landscape architecture	Address 1148 N. Cherokee Rd		Resource Use Vacant Date of Construction 1965-1974		
		H B C C S S S S S S S S S S S S S S S S S	Date of Construction 1905-1974 House Type Ranch Barn Type Church Type Church Type Commercial Type School Type Structural System Balloon Frame Style No academic style Roof Hip Exterior Cladding Brick: Running bond Foundation Continuous: Brick Porch Portico Windows Double hung sash: 2/2 Chimney No chimney observed		
			Iterations Additions		
Preliminary A	Assessment	Status - Listed	Applicable Criteria		
Not El	igible	Not listed	с		



	Social Circle Historic Resource		NARGHIS ID	240560
V OF CF	Resource ID SC 326	F	Resource Type	Building
	Address 1096 N. Cherokee	Rd	Resource Use	Residential: Single family dwelling
A landscape architecture historic preservation			Date of Construe	ction ¹⁹³⁰⁻¹⁹³⁹
H env. planning + design SC H environmental ethics	County Walton	H	louse Type	Side gable cottage
		E	Barn Type	
	Maria n Ville Ville		Church Type	
X & L			Commercial Typ	e
		e 🖉	School Type	
1998 A	Alt The Alter		Structural Syste	m Balloon Frame
		.	Style No	academic style
MARKED		F	Roof Gat	ble: side
			Exterior Claddin	g Synthetic siding: vinyl
	111/	F	oundation Cor	tinuous: concrete
Carlos and	State State	PERSONAL PROPERTY IN THE PERSON PROPERTY INTERPERTY INTO PROPERTY PROPERTY INTO PROPERTY PROPERTY INTO PROPERTY	Porch Por	tico
	and the second		Vindows Dou	ible hung sash: 3/1
Sec.			Chimney No	chimney observed
			Alterations Rep	placement materials
Preliminary As	sessment	Status - Listed		Applicable Criteria
Potentially		Not listed		c

	Social Circle Historic Resource Resource ID SC-327			0561 Building
	Address 1088 N. Cherokee I			Commercial: single retail
Nandscape architecture			Date of Construction	on ¹⁹³⁰⁻¹⁹³⁹
H env. planning + design SC H environmental ethics	County Walton		House Type	
	*	12	Barn Type	
			Church Type	
N-DAS			Commercial Type	Commercial: single retail
			School Type	
			Structural System	Concrete block
		Design of the second seco	Style No aca	ademic style
			Roof Gable:	: Parapet
			Exterior Cladding	Concrete: block
2433			Foundation Contin	uous: concrete
			Porch No por	rch observed
			Windows Double	e hung sash: 6/6
			Chimney Center	r within roof surface: brick
			•	addition
	ssassmant	Status - Listed		pplicable Criteria
Proliminary A	SSESSITIETIL	Not listed		C
Preliminary A	nible			0
Preliminary A Not Eli	gible			
-	gible			
-	gible	Hot listed		



Resource ID SC 328


Address 1040 N. Cherokee Rd

County Walton



Building **Resource Type Resource Use** Residential: Single family dwelling Date of Construction 1934-1945 Bungalow: front gable House Type Barn Type Church Type **Commercial Type** School Type Structural System Balloon Frame Style Craftsman: elements of style Gable: front Roof Exterior Cladding Brick: Veneer Foundation Continuous: brick Portico Porch Double hung sash: 4/4 Windows Chimney No chimney observed Replacement materials Alterations


Preliminary Assessment	Status - Listed	Applicable Criteria
Not Eligible	Not listed	С



INVIRO	Resource ID SC 330
+D architecture +D	Address 876 Tower Rd.
eservation DESIGN ng + design DESIGN ntal ethics	County Walton
	. 11
allin	
and the	

Resource Ty	pe Building
Resource Us	e Residential: Single family dwelling
Date of Cons	struction ¹⁹⁶⁵⁻¹⁹⁷⁴
House Type	Ranch
Barn Type	
Church Type	9
Commercial	Туре
School Type	
Structural S	ystem Post and beam
Style	No academic style
Roof	Нір
Exterior Cla	dding Brick: running bond
Foundation	Continuous: brick
Porch	Stoop
Windows	Double hung sash: 1/1
Chimney	No chimney observed
Alterations	


Preliminary Assessment	Status - Listed	Applicable Criteria	
Not Eligible	Not listed	С	



	Social Circle Historic Resource		NARGHIS ID 240597		
TY OF GENVIR	Resource ID SC-332		Resource Type Building		
andscape architecture	Address 752 N Cherokee Rd		Resource Use Residential: Single family dwelling Date of Construction 1950-1959		
D historic preservation D H env. planning + design S H environmental ethics	County Walton		House Type Bungalow: side gable Barn Type		
			Church Type Commercial Type School Type		
			Structural System Balloon Frame Style No academic style Roof Gable: side		
-			Exterior Cladding Synthetic sidiing; vinyl Foundation Continuous: brick Porch Verandah; Portico		
			WindowsDouble hung sash: 1/1ChimneyGable end exterior: brickAlterationsReplacement materials		
Preliminary	Assessment	Status - Listed	Applicable Criteria		

 Preliminary Assessment
 Status - Listed
 Applicable Criteria


 Not Eligible
 C




C E C D C C C C C C C C C C C C C C C C	Resource ID SC-334
C E + D landscape architecture	Address 192 Rose Ln
 historic preservation DESIGN env. planning + design SGN environmental ethics 	County Walton


Resource Ty	pe Building
Resource Us	e Residential: Single family dwelling
Date of Cons	struction ¹⁹⁵⁰⁻¹⁹⁵⁹
House Type	Ranch
Barn Type	
Church Type)
Commercial	Туре
School Type	
Structural S	ystem Post and beam
Style	No academic style
Roof	Нір
Exterior Cla	dding Brick: running bond
Foundation	Concrete: continuous
Porch	Stoop
Windows	Double hung sash: 2/2
Chimney	No chimney observed
Alterations	


Preliminary Assessment	Status - Listed	Applicable Criteria	
Not Eligible	Not listed	С	




Preliminary Assessment	Status - Listed	Applicable Criteria	
Not Eligible	Listed	С	











	Social Circle Historic Resource	NARGHIS ID 240606
OLLEGE OF ENVIR	Resource ID SC-343	Resource Type Building
	Address 137 Cherokee Rd	Resource Use Commercial: Healthcare
I landscape architecture T+ O historic preservation DE B env. planning + design Sic E environmental ethics O	County Walton	Date of Construction ¹⁹⁰⁰⁻¹⁹⁰⁹ House Type
► environmental etnics 2		Barn Type Barn Type Church Type Commercial Type Commercial block: Multiple retail School Type Structural System Balloon frame Style Colonial revival Roof Flat Exterior Cladding Stucco Foundation Unknown Porch Recessed Windows Fixed
		Chimney No chimney observed Alterations
Preliminary A Not E		Similary .
Not E		Alterations Applicable Criteria
-	igible Not listed	Alterations Applicable Criteria C
Not E	igible Not listed Social Circle Historic Resource Resource ID SC-344	Alterations Applicable Criteria C NARGHIS ID 240933 Resource Type Building Resource Use Commercial: Office
	igible Not listed Social Circle Historic Resource	Alterations Applicable Criteria C NARGHIS ID 240933 Resource Type Building

Preliminary Assessment

Eligible

Status - Listed

Listed

Exterior Cladding

Porch

Windows

Chimney

Alterations

Foundation Unknown

Portico

Stucco

Double hung sash: 6/6

No chimney observed

Replacement materials


Applicable Criteria


С





Preliminary Assessment	Status - Listed	Applicable Criteria
Not Eligible	Listed	С






Not listed

С


Not Eligible






Resource Ty	pe Building			
Resource Us	Residential: Single Family Dwelling			
Date of Cons	struction ¹⁹²⁵⁻¹⁹³⁴			
House Type	Bungalow: front gable			
Barn Type				
Church Type)			
Commercial	Туре			
School Type				
Structural Sy	ystem Balloon Frame			
Style	Craftsman			
Roof	Gable: front			
Exterior Cla	dding Synthetic siding: vinyl			
Foundation	Continuous: brick			
Porch	Stoop: front			
Windows	Double hung sash: 1/1			
Chimney	Center ridgeline: brick			
Alterations	Material replacements			


Preliminary Assessment	Status - Listed	Applicable Criteria	1
Eligible	Listed	С	





Preliminary Assessment	Status - Listed	Applicable Criteria	
Eligible	Listed	С	





Social Circle Historic Resource Resource ID SC-355 Address 130 W Hightower Tr County Walton Margel IS ID 65128 NARGHIS ID 65128 Resource Use Residential: Single Date of Construction 1930-1939 House Type Bungalow: side gat Barn Type Church Type Commercial Type	
School Type Structural System Ballon frame Style Craftsman Roof Gable: side Exterior Cladding Wood: weather Foundation Continuous: brick Porch Portico Windows Double hung sash: 3/1,	therboard 1, 1/1
Chimney Off center ridgeline: brid Alterations Screened side porch	пск
Preliminary Assessment Status - Listed Applicable Crite Eligible Listed C	teria



Resource ID SC-356

Address 144 W Hightower Tr

County Walton



NARGHIS	ID 242524
Resource Ty	pe Building
Resource Us	Residential: Single family dwelling
Date of Cons	struction ¹⁹³⁰⁻¹⁹³⁹
House Type	Bungalow: side gable
Barn Type	
Church Type)
Commercial	Туре
School Type	
Structural Sy	ystem Balloon frame
Style	Craftsman
Roof	Gable: side
Exterior Cla	dding Synthetic siding: vinyl
Foundation	Continuous: brick
Porch	Portico
Windows	Double hung sash: 3/1
Chimney	Off center ridgeline: brick
Alterations	Material replacement, porch enclosure

Preliminary Assessment	Status - Listed	Applicable Criteria	
Eilgible	Listed	С	





Resource ID SC-358

Address Approximately 180 W Hightower Tr

County Walton



NARGHIS ID 242525

Resource Type	Building				
Resource Use	Educational: school				
Date of Construction 1955-1964					
House Type					
Barn Type					
Church Type					
Commercial Ty	pe				
School Type	School building: multi-wing				
Structural System	em Poured concrete				
Style Mo	oderne				
Roof Fla	at				
Exterior Claddi	ng Concrete				
Foundation Co	ontinuous: concrete				
Porch No	No porch observed				
Windows Fix	Fixed, Double hung sash: 1/1				
Chimney No	chimney observed				
Alterations Mu	ultiple additions				

Preliminary Assessment Not Eligible Status - Listed Not listed Applicable Criteria

	Social Circle Historic Resource		NARGHIS ID 65144
30 JO AL	Resource ID SC-359		Resource Type Building
andscape architecture	Address 296 W Hightower T	r	Resource Use Residential: Single family dwelling Date of Construction ¹⁸⁸⁹
 historic preservation H env. planning + design H environmental ethics 	County Walton		House Type Queen Anne cottage
			Barn Type Church Type Commercial Type School Type
			Structural SystemBalloon frameStyleFolk VictorianRoofComplexExterior CladdingWood: weatherboard
			FoundationPier with infill: brickPorchVerandah
			WindowsDouble hung sash: 4/4, 6/6ChimneyOff center within roof surface: brickAlterations
Preliminary A Eligit		Status - Listed Listed	Applicable Criteria C



Resource ID SC-360

Address 308 W. Hightower Tr

County Walton



Building **Resource Type Resource Use** Residential: Single family dwelling Date of Construction 1885-1894 Queen Anne house House Type Barn Type Church Type **Commercial Type** School Type Structural System Balloon frame Style Queen Anne Roof Complex Exterior Cladding Wood: weatherboard Foundation Pier with infill: brick Porch Wrap around; balcony Fixed, Double hung sash: 25/1, 1/1 Windows Chimney Multiple random Alterations

Preliminary Assessment	Status - Listed	Applicable Criteria
Eligible	Listed	С






Resource Ty	pe Building		
Resource Us	se Residential: Single family dwelling		
Date of Cons	struction ¹⁸⁸⁰⁻¹⁸⁸⁹		
House Type	Side hallway		
Barn Type			
Church Type	ę		
Commercial	Туре		
School Type			
Structural System Balloon frame			
Style	Italiante		
Roof	Pyramidal		
Exterior Cla	dding Wood: weatherboard		
Foundation	Continuous: brick		
Porch	Verandah, stoop		
Windows	Double hung sash: 2.2, Triple hung sash		
Chimney	Off center within roof surface: brick (2)		
Alterations	Historic additions		

Preliminary Assessment	Status - Listed	Applicable Criteria	
Eligible	Listed	С	

оринания и принатики и прин Принатики и принатики и прин	Deserves ID, co. co.		December Tru	Building
	Resource ID SC-363		Resource Typ	
C E+D	Address 511 W Hightower T	r 🔰	Resource Use	
historic preservation PESIG env. planning + design GN environmental ethics N	County Walton		Date of Cons	Side hallway
environmental ethics 🕇			House Type	olde hallway
	AND AND AND	KAR A	Barn Type	
	the states with	A A A	Church Type	Бира
			Commercial	туре
X		NA XAR	School Type	stem Balloon frame
2 AV			Structural Sy	Italianate
23 H 1			Otyle	Hip
			Exterior Clad	•
				Pier with infill: brick
				Stoop
				Double hung sash: 2/2, Fixed
	a state of the			Off center within roof surface: brick
	Contraction and		ommey	Historic addition
			Alterations	
Preliminary As	sessment	Status - Listed		Applicable Criteria
Eligibl		Listed		C






Building **Resource Type** Residential: Single family dwelling **Resource Use** Date of Construction ¹⁹⁰⁵⁻¹⁹¹⁴ Georgian cottage House Type **Church Type Commercial Type** School Type Balloon frame **Structural System** No academic style Hip **Exterior Cladding** Synthetic siding: hip Foundation Pier with infill: brick Verandah Double hung sash: 4/4 Off center within roof surface: brick (2) Material replacements, additions Alterations

Preliminary Assessment Not Eligible Status - Listed

Applicable Criteria






NARGHIS ID 242537

Resource Ty	pe Building		
Resource Us	se Residential: Single family dwelling		
Date of Cons	struction ¹⁹¹⁵⁻¹⁹²⁴		
House Type	Bungalow: side gable		
Barn Type			
Church Type)		
Commercial	Туре		
School Type			
Structural System Balloon frame			
Style	No academic style		
Roof	Gable: side		
Exterior Cla	dding Synthetic siding: vinyl		
Foundation	Continuous: brick		
Porch	Verandah		
Windows	Double hung sash: 1/1		
Chimney	No chimney observed		
Alterations	Material replacements, additions and alterations		

Preliminary Assessment Not Eligible Status - Listed Listed Applicable Criteria





Resource ID SC-368

Address 324 Cedar St

County Walton



	1
NARGHIS	ID 242539
Resource Ty	pe Building
Resource Us	e Residential: Single family dwelling
Date of Cons	struction ¹⁹¹⁰⁻¹⁹¹⁹
House Type	Saddlebag
Barn Type	
Church Type	
Commercial	Туре
School Type	
Structural Sy	/stem Balloon frame
Style	No academic style
Roof	Gable: side
Exterior Clac	ding Synthetic siding: vinyl
Foundation	Pier with infill: brick
Porch	Verandah
Windows	Double hung sash: 4/4, 6/6
Chimney	No chimney observed
Alterations	Replacement materials, alterations and addition
_	

Preliminary Assessment	Status - Listed	Applicable Criteria	
Not Eligible	Listed	С	



Resource ID SC-369

Address 254 Cannon Dr

County Walton



NARGHIS ID 242540

Building **Resource Type** Residential: Single family dwelling **Resource Use** Date of Construction ¹⁹¹⁰⁻¹⁹¹⁹ Saddlebag: 2 door House Type Barn Type **Church Type Commercial Type** School Type Balloon frame **Structural System** No academic style Style Gable: side Roof **Exterior Cladding** Synthetic siding: vinyl Foundation Pier with infill: brick Porch Verandah Double hung sash: 6/6 Windows Center: brick Chimney Replacement materials, alterations Alterations

Preliminary Assessment Not Eligible Status - Listed

Applicable Criteria



Social Circle Historic Resource

Resource ID SC-370

Address 412 Spring St

County Walton



NARGHIS ID 242541

Resource Ty	pe Building		
Resource Us	Residential: Single family dwelling		
Date of Cons	struction ¹⁸⁸⁰⁻¹⁸⁸⁹		
House Type	l-house		
Barn Type			
Church Type)		
Commercial	Туре		
School Type			
Structural System Balloon frame			
Style	No academic style		
Roof	Gable: side		
Exterior Cladding Synthetic siding: vinyl			
Foundation	Unknown		
Porch	Unknown		
Windows	Double hung sash 6/6, Single hung sash		
Chimney	Gable end exterior: brick		
Alterations	Multiple additions, replacement materials		

 Preliminary Assessment
 Status - Listed
 Applicable Criteria

 Not Eligible
 Listed
 C

Bibliography

- . "Georgia Historic Resources Survey Manual," Atlanta: Georgia Department of Natural Resources, Historic Preservation Division, 2000.
- <->. Georgia's Living Places: Historic Houses in their Landscaped Setting (1991), http://georgiashpo.org/sites/uploads/hpd/pdf/NR15arch_20080521100904_optimized.pdf (accessed September 10, 2012).
- <>. "How to Apply the National Register Criteria for Evaluation: National Register Bulletin 15," (Washington, D.C. : U.S. Government Printing Office, Department of the Interior, National Park Service, 1997.) http://www.nps.gov/nr/publications/bulletins/pdfs/nrb15.pdf
- Anderson Cordova, Karen and Burns, Leigh. *Preservation Primer: A Resource Guide for Georgia*. Atlanta: Georgia Department of Natural Resources, HPD, 2011.
- Ching, Frank. A Visual Dictionary of Architecture, New York : Van Nostrand Reinhold, 1995.
- Cloues, Richard. *The Ranch House in Georgia: Guidelines for Evaluation* Historic Preservation Division; available at http://issuu.com/georgiashpo/docs/ranch_house_guidelines?mode=windo w&backgroundColor=%2322222 (Accessed October12, 2012).
- Derry, Anne, Jandal, H. Ward, Shull, Carol D., and Thorman, Jan. "Guidelines for Local Surveys: A Basis for Preservation Planning. National Register Bulletin 24," Washington, D.C: U.S. Government Printing Office, Department of the Interior, National Park Service, 1985.) http://www.nps.gov/nr/publications/bulletins/pdfs/nrb24.pdf
- Lambin, Jeanne. "Preserving Resources from the Recent Past," Washington, D.C.: National Trust for Historic Preservation, 2007
- Lavandier, Jessica. "Fulton County Historic Resources Survey, North Fulton County Executive Summary," Georgia Department of Natural Resources, HPD, 1996.
- McAlaster, Virginia and Lee. A Field Guide to American Houses, New York: Alfred A, Knopf, Inc, 2003.



The University of Georgia College of Environment + Design Center for Community Design & Preservation Phase I Historic Resource Survey Social Circle, Georgia August 2012